

Current Date 03Jan2020

380G LC FT4 EXCAVATOR

HYDRAULICS:

Open Center, Load Sensing with Variable Displacement Pumps

Hydraulic Pilot Controls Axial Piston Swing Motor Multiple Wet Disk Swing

Brake

Auxiliary Valve Section Adjustable Flow for Attachments Through

Monitor

Boom and Arm Reduced Drift

Valves

Auto Power Lift

Hydraulic Tank Site Gauge 5,000 Hour Hydraulic Oil

Change Interval

Hydraulic Oil Sampling Valve

UNDERCARRIAGE: 32 In. (800 mm) Triple

Grouser Shoes

Two Speed Propel with Auto-

Shift

Axial Piston Propel Motors Propel Motor Shields Planetary Final Drives Sealed Track Chain Three Track Guides Provisions for Tie Downs

X-Frame Car Body

Hydraulic Track Adjuster Eight Lower Rollers

Two Upper Rollers Spring Applied Hydraulic

Released Propel Brake
UPPER STRUCTURE:

Right, Left and

Counterweight Mirrors

Toolbox

Vandal Locks for:

Cab Door Service Doors

Tool Box

Counterweight, 16,819 lbs.

(7,629 kg) Work Lights: Debris Screening Side Panel Remote Mounted Engine Oil and Fuel Filters

Handrails

FRONT ATTACHMENT:

Oil Impregnated Bushings Reinforced Resin Thrust

Plates

Tungsten Carbide Thermal Coating on arm to Bucket

Joint

Centralized Lubrication

System

Dirt Seals on Bucket Pins

Less Boom Less Arm Less Bucket

OPERATOR'S STATION: Adjustable Control Positions (Levers to Seat, Seat to

Pedals)

4" Arm Rests Attached to

Side Consoles

Pilot Control Shut-Off Lever Short Stroke, Low Effort Pilot

Levers

Switches for Auxiliary

Hydraulic Control on RH Pilot

Lever

Deluxe Adjustable Cloth Seat with Suspension, Reclining

Backrest,

Headrest, and Adjustable

Lumbar Support

Multifunction, Color LCD Monitor System with: Diagnostic Capability Systems Monitoring

Capability

Multiple Language Capability

Maintenance Tracking Engine Coolant Temperature

Gauge

Engine Coolant Temperature Warning Indicator with

Audible Alarm

Fuel Gauge with Low Fuel Indicator

Diesel Exhaust Fluid Gauge

Work Mode Indicator
Auto Idle Indicator

Alternator Charge Indicator

Air Filter Restriction

Indicator

Fault Code Alert Indicator Check Engine Indicator Wiper Mode Indicator Work Lights On Indicator

Fuel Rate Display

Clock

Hour Meter Mode Selection:

One Work Mode Three Power Modes

Numerous Attachment

Modes

Auto-Climate Control/Air

Conditioner, Heater with

Pressurizer AM-FM Radio Rear view camera

Control Pattern Changer
Machine Information Center

(MIC)

Windshield Wiper/Washer with Intermittent Speed

12V-60W, 5 Amp Cell Phone

Power Outlet

2 In. Retractable Seat Belt

Tinted Safety Glass

Hot/Cold Box Compartment

Horn

Two Cup Holders Interior Light Coat Hook Floor Mat

Motion Alarm with Cancel

Switch

Transparent Tinted Roof Hatch with Sunshade Four Fluid-Filled Elastic

Mounts

One Mounted on Frame One Mounted on Boom

Engine Oil Pressure Warning Indicator with Audible Alarm

Easy Access Air Conditioning Filter

Required - You must select one from each category

BASE MACHINE

F.O.B Kernersville, North Carolina for Complete Machine.

See DEALER-INSTALLED ATTACHMENT section for additional source notes.

Description Code Price 380G LC FT4 EXCAVATOR OBKOFF \$348,517.00

ENGINE

Description Code Price 1095 **Engine Stage IV Emissions** \$38,595.00

John Deere PowerTech PSS 9.0L 271 Net Rated hp (ISO 9249) Series Turbocharged Charge Air Cooler Electronic Engine Control Unit

Auto-Idle System

Cool on Demand Hydraulic Driven Fan

Antifreeze Protection to -34F (-37C)

Enclosed Fan Guard

A/C Condenser and Fuel Cooler

Dual Element Dry-type Air Filter with Restriction Indicator

Full Flow Oil Filter Double Fuel Filter Water Separator

Underhood Diesel Particulate Filter with Curved Exhaust

Automatic Belt Tension Device

Heavy Duty, Low Maintenance Batteries

80-Amp Alternator - 24 Volt

500 Hour Engine Oil Change Interval

70% (35 degrees) Off Level Capability

Engine Oil Sampling Valve

OPERATOR'S MANUAL AND DECALS

Non-English Operator's Manuals

Translated Customer Delivery Packets can be ordered using the John Deere Technical Information Bookstore at http://www.johndeeretechinfo.com at no charge. The Translated Delivery Packets include the Operator Manual, Decal Kit, Warranty Information Booklet, and Uptime Maintenance Planner. Search for and order the Translated Delivery Packets by model and language that meets your customer requirements. A listing of all Translated Delivery Packets available can be found by selecting Translated Delivery Packets from the Manual Type dropdown list. Technical support is available by calling 1-866-213-3373.

Description Price Code 1600 No Added Cost English Customer Delivery Packet

English Decals and Customer Delivery Packet

MACHINE CONNECTIVITY

Machine connectivity functions require cellular coverage. Usage of JDLink /ZXLink System requires customer's

John Deere 380G LC FT4 Excavator -Mid Size-1/3/20

acceptance of the terms of the John Deere Telematics System Contract.

Option availability limited by specific geographical regions. Please refer to region specific price pages for appropriate ordering codes.

Description Code Price JDLink Ultimate - 5 Year Subscription 170C No Added Cost

Includes JDLink hardware: integrated cab wiring harness, antenna, modular telematics gateway (MTG), and now includes all Ultimate Connectivity features Wireless Data Transfer (WDT) enabling automatic data transfer from TimberMatic and Waratah H16 Measuring Systems to TimberManager and MyJohnDeere, supporting TimberOffice 5 Software. Additionally, Ultimate now includes Limited Internet features supporting optional ForestSight Solutions such as advance mapping systems and Remote Display Access (RDA) features supported by TeamViewer applications. JDLink utilizes cellular and satellite technology infrastructure that is outside the control of John Deere. Changes to that infrastructure may require customers to purchase compatible JDLink hardware to restore functionality. Includes 5 year subscription. Annual subscription renewal required after 5 years for continued functionality. JDLink customer account must be created to access JDLink Ultimate data. Go to www.StellarSupport.com to renew or update JDLink subscriptions. Use of this service, and all rights and obligations of John Deere and the Customer (as identified in the applicable agreement), are governed by the terms and conditions outlined in the applicable Services and Software agreements available at www.JohnDeere.com/Agreements. If these terms and conditions are not agreeable do not proceed and do not use the

TRACK SHOE	S
TRACK SHOE	

Description 700 mm (28 In.) Single-Bar, Heavy-Duty Chain and Shoes	Code 3320	Price \$9,056.00
Recommended for use only in mountainous terrain.		
800 mm (32 In.) Triple-Bar, Heavy-Duty Chain and Shoes	3370	\$9,056.00
Recommended for general conditions and soft terrain.		
SEAT		
Description	Code	Price

Description	Code	Price
Seat, Standard Mechanical	4125	No Added Cost
Seat, Heated Air-Suspension	4130	\$976.00
Seat, Premium Leather - Thermal Heating and Active Cooling	4135	\$2,731.00
Active heating and cooling Air suspension High seat back 3-way adjustability		

High visability orange 3 inch seat belt **BOOM**

> Description Code Price No Added Cost 6801

I	ess	R	\cap	\cap	m	١

Excludes Arm Cylinder, Boom Cylinders and Plumbing on Boom. Includes Pin Connecting Boom to Mainframe and the Two Boom Cylinder Pins.
Requires code 7001, "Less Arm".
The "Hydraulic Filter Restriction Indicator" in DEALER-INSTALLED ATTACHMENTS is recommended

One Piece Boom with Arm Cylinder and Plumbing 6835 \$30,874.00

One Piece HD Boom with Arm Cylinder and Plumbing

w	ARM	1

Description Code Price Less Arm, Bucket Cylinder, Bucket Linkage and All 7001 No Added Cost Attaching Pins and Hoses Hydraulic Filter Indicator Recommended. Requires code 8001, Less Buckets. Arm with Bucket Cylinder and Linkage 7222 \$22,839.00 3.2 M (10 ft. 6 in.) HD Arm 7267 Arm with Bucket Cylinder and Linkage \$22,839.00

Not recommended for impact (hammer) or high density material applications. 4.0 M (13 ft. 1 in.)

AUXILIARY HYDRAULICS

for 4.0 M Arm

Includes Combination piping

		AUXILIARY HYDRAULICS
Price No Added Cost	Code 7401	Description Less Auxiliary Hydraulics
\$10,530.00	7420	Auxiliary High-Flow Hydraulic w/ 2-Way Foot Controller
		Includes Combination piping for 3.2 M Arm (10 ft. 6 in.)
\$10,536.00	7430	Auxiliary High-Flow Hydraulic w/ 2-Way Foot Controller
		Includes Combination piping for 4.0 M Arm
\$8,108.00	7450	Auxiliary High-Flow Hydraulic Lines Only
		for 3.2 M Arm Requires a control circuit such as a foot controller or the standard right- hand control handle with (2) switches. Also order a solenoid kit. Includes Combination piping
\$8,217.00	7460	Auxiliary High-Flow Hydraulic Lines Only

Requires a control circuit such as a foot controller or the standard righthand control handle with (2) switches. Also order a solenoid kit.

	Auxiliary High-Flow Hydraulic Lines w/ AFL (Pilot Lever Proportional Control)	7490	\$11,550.00
	Includes Combination piping for 3.2 M Arm		
	Auxiliary High-Flow Hydraulic Lines w/ AFL (Pilot Lever Proportional Control)	7495	\$11,556.00
	for 4.0 M Arm Includes Combination piping		
_	BUCKETS		
	All Heavy-Duty and Severe-Duty Buckets come standard with TK-Series Fanggs Te	eeth.	
	Description	Code	Price
	Less Bucket	8001	No Added Cost
	Includes bucket mounting pins.		
	Heavy-Duty Bucket	8340	\$13,063.00
	Includes Six (6) John Deere TK-Series Fanggs Teeth (TK450FD). 48 In. (1220 mm), 1.96 Yd3 (1.50 M3) Heavy-Duty Bucket		
	Heavy-Duty Bucket	8350	\$13,992.00
	Includes Six (6) John Deere TK-Series Fanggs Teeth (TK450FD). 54 In. (1375 mm), 2.27 Yd3 (1.74 M3) Heavy-Duty Bucket		
	Severe Duty Bucket	8453	\$17,772.00
	54 In. (1375 mm) 02.27 Yd3 (1.74 M3) Severe Dury Bucket Includes Five (5) ESCO Ultralok Teeth, Side Shrouds and Wear Protectors		
	Heavy Duty Bucket	8454	\$16,336.00
	60 In. (1525 mm) 2.57 Yd3 (1.96 M3) Includes Six (6) ESCO Ultralok Teeth		
da	ional - Select as desired		
~	HEATER		
	Description	Code	Price
	Engine Block Heater	9015	\$248.00
~	ETHER STARTING AID		
	Description	Code	Price
	Ether Start Aid	9030	\$347.00
~	FILTER		
	Description	Code	Price
	Fuel Filter, Severe-Duty	9060	\$175.00

	Engine Air Centrifugal Pre-Cleaner	9070	\$631.00
	Recommended for harsh conditions		
~	ENGINE FAN		
	Description	Code	Price
	Automatic Reversing Cooling Fan	9115	\$1,782.00
	Features selectable intervals and manual override. For use in environments with airborne debris.		
	Single Pedal Propel	9180	\$2,259.00
~	EXHAUST		
	Description	Code	Price
	Chrome Exhaust	9700	\$445.00
~	SHIPPING PREPARATION		
	Description	Code	Price
	Special Export Preparation Do not install front for shipping	9803	No Added Cost
	For Export Containerization		
_	UNDERCARRIAGE		
	Description	Code	Price
	Track Frame Undercover	9160	\$643.00
~	LIGHT PACKAGE		
	Description	Code	Price
	Light Package	9150	\$2,258.00
	 All exterior machine lights are LED 2 Front Cab lights, 1 Rear Cab light, 1 Toolbox Light, 1 Under Engine Hood Light, 1 Left hand and 1 Right hand Boom Lights 		
~	BOOM CYLINDERS		
	Description	Code	Price
	Boom Cylinders with Plumbing to Main Frame	9010	\$7,697.00
	Requires 6801, Less Boom, and Code 7001, Less Arm.		

▼ ATTACHMENTS FOR FIELD CONVERSION

F.O.B. Dubuque, lowa for dealer-installed kits, except where noted. Some of the following kits may require additional parts for a complete installation. Prior to ordering, check the installation instructions by going to www.johndeeretechinfo.com and clicking on Library, or by clicking on this Hyperlink (Installation Bulletin Search), and insert the AT number to retrieve the attachment installation instruction bulletin for additional parts. Exception to above note is FRONTIER Dealer Installed Kits.

All attachments are sold as a quantity of one.

Description	Code	Price
Buckets, Heavy-duty	DVT111/7	
36 In (914 mm), 1.37 yd3 (1.05 M3) Heavy-Duty Bucket	BYT11167	\$8,483.00
Includes Four (4) John Deere TK-Series Fanggs Teeth (TK450FD)		
42 In (1067 mm), 1.66 yd3 (1.27 M3) Heavy-Duty Bucket	BYT11168	\$9,057.00
Includes Four (4) John Deere TK-Series Fanggs Teeth (TK450FD).		
48 In (1219 mm), 1.96 yd3 (1.50 M3) Heavy-Duty Bucket	BYT11169	\$9,706.00
Includes Five (5) John Deere TK-Series Fanggs Teeth (TK450FD		
54 In (1372 mm), 2.27 yd3 (1.74 M3) Heavy-Duty Bucket	BYT11170	\$10,502.00
Includes Five (5) John Deere TK-Series Fanggs Teeth (TK450FD)		
54 in.(1372 mm) 2.27 yd3 (1.74 M3) SD Bucket	BYT11172	\$12,382.00
Includes Five (5) John Deere TK-Series Teeth (TK550SD). Also include Side Shrouds and Wear Protectors.		
60 In (1524 mm), 2.57 yd3 (1.96 M3) Heavy-Duty Bucket	BYT11171	\$11,380.00
Includes Six (6) John Deere TK-Series Teeth (TK450)		
Buckets, Side Cutters		
Edge Protector Kit	AT342511	\$618.00
Side-Cutter Kit, 3 inch	AT342512	\$641.00
Side-Cutter Kit, 6 inch	AT342513	\$641.00
<u>Guards</u>		
Cab FOPS Guard	AT419609	\$4,413.00
FOPS Level II, ISO 10262 Certified		
Hydraulic Couplers		
Hydraulic Quick Coupler	AT452020	\$10,812.00
Installation Charge for Hydraulic Coupler	AT345608	\$1,387.00
Installation Charge Order also requires attachment part number, SHIP-TO address for Paladin Custom Works, AND reference related machine order number. The related machine order must reference the attachment order number.		
Order code available only for Kernersville, North Carolina installations.		
<u>Hydraulic Thumb Kits</u>		
Deere/Hitachi Hydraulic Thumb Installation	AT339844	\$1,967.00

Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Direct for Couplers Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Progressive AT379662 \$12,639. Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (131*1) Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639. Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (131*1) Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153004 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp	Labor for installation of Deere/Hitachi thumb at Paladin Customworks Kernersville, NC.		
width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Direct for Couplers AT379661 \$11,118.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Progressive AT379662 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (1311) Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (1311) Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT33280 Hydraulic Hose M44280 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,380GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44280 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14053698 Clamp 1407404 Washer (2 used) 4053698 Clamp	Hydraulic Thumb Kit, Direct	AT379660	\$11,118.00
engagement. Hydraulic Thumb Kit, Direct for Couplers Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Progressive AT379662 \$12,639.0 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13*1*) Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.0 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13*1*) Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		cket	
Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Progressive AT379662 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1') Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1') Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.0 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M74140 Washer (2 used) 4053698 Clamp 14M741740 Washer (2 used) 4053698 Clamp	· · · · · · · · · · · · · · · · · · ·	h	
width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Hydraulic Thumb Kit, Progressive AT379662 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.1 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp	Hydraulic Thumb Kit, Direct for Couplers	AT379661	\$11,118.00
engagement. Hydraulic Thumb Kit, Progressive AT379662 \$12,639.4 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1') Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.4 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1') Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		cket	
Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.1 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		h	
width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (131") Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.0 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (131") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.0 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp	Hydraulic Thumb Kit, Progressive	AT379662	\$12,639.00
engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulic Thumb Kit, Progressive for Couplers AT379663 \$12,639.4 Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		cket	
Hydraulic Thumb Kit, Progressive for Couplers Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3, ZX350LC-5, ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		h	
Teeth matching between the bucket and thumb will depend on the bucket width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.0 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp	Only available for the following arm lengths: 350/380 4.0M (13'1")		
width, number of teeth, and tooth spacing. Please see DMAC solution 94331 for optimum thumb and bucket teeth engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.0 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp	Hydraulic Thumb Kit, Progressive for Couplers	AT379663	\$12,639.00
engagement. Only available for the following arm lengths: 350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.4 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		cket	
350/380 4.0M (13'1") Hydraulics Anti-Drift Valve with Plumbing and Hardware, Arm AT327659 \$3,100.0 Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		h	
Anti-Drift Valve with Plumbing and Hardware, Arm Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp			
Cylinder For ZX350LC-3,ZX350LC-5,ZX380LC-5N machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp	<u>Hydraulics</u>		
following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp		AT327659	\$3,100.00
24M7404 Washer (2 used) 4053698 Clamp	following parts: AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp 14M7415 Nut M12 24M7404 Washer (2 used) 4053698 Clamp For 350DLC,350GLC,380GLC machines also order the following parts AT332580 Hydraulic Hose M44269 Spacer T153064 Clamp	5:	
<u>·</u>	24M7404 Washer (2 used)		
Auxiliary High-Flow Hydraulic Lines for 350G & 380G AT390767 \$6,986.	<u> </u>	AT390767	\$6,986.00

Bid Term: 2/20/19 - 2/19/21

Includes 1 In. diameter lines from the auxiliary spool in main control valve along the boom ending on the arm and 1.25 In. return line routed directly to return filter piping for low pressure return. Also includes 2 relief valves and 2 shutoff valves located on end of arm. Recommend Hydraulic Filter Restriction Indicator Kit.		
Boom Cylinder Anti-Drift Valve with Plumbing and Hardware	AT438678	\$3,567.00
Control Handle for Auxiliary Hydraulics, Left-Hand	AT327652	\$525.00
Requires control solenoid for either 1-way or 2-way auxiliary hydraulics. Recommended for use with auxiliary hydraulic lines.		
Control Solenoid for 1-way Auxiliary Hydraulics with Foot Switch	AT446156	\$950.00
Does not use the monitor for flow control. Does not require solenoids for auxiliary hydraulics. Includes foot switch, solenoid, wiring, and hoses.		
Control Solenoids for 2-Way Auxiliary Hydraulics	AT445530	\$800.00
Monitor can be used to control hydraulic flow. Can be used with either right-hand or left-hand control handle.		
Hydraulic Filter Restriction Indicator Kit	AT445803	\$789.00
Two-Pump Combined Flow Piping	AT358596	\$1,674.00
For attachments that require additional hydraulic flow. Do not use with DPF Load Valve kit ETN92604.		
Operator Environment		
Exterior Work Lights Package	AT396663	\$741.00
Additional 2 Cab lights, with 1 Right hand Boom Light.		
Full Length Front Guards	BYT11141	\$1,532.00
Stereo adapter for phone or music device.	ETN93549	\$224.00
Applicable for machines before SN 1FF380GXHJF900300		
Overall Vehicle		
Vandal Covers	BYT11005	\$3,023.00
After Serial # 00300		
Powertrain & Cooling		
Automatic Reversing Cooling Fan	AT449123	\$2,030.00
Features selectable intervals and manual override. For use in environments with airborne debris. Installation time 2 hours.		
REFERRAL ATTACHMENTS		
Description	Code	Price

G.r.mfg.

G.R. Manufacturing, Inc. * Kits listed below must be ordered through John Deere. * F.O.B. Trussville, Alabama * All kits include installation instructions * All warranty, repair parts, technical support and assistance, and sales support and assistance will be the responsibility of G.R. Manufacturing, Inc., and will be handled directly between the Dealer and G.R. Manufacturing, Inc. G.R. Manufacturing, Inc. 4800 Commerce Drive Trussville, Alabama 35173 Phone: (800)841-8001 Fax: (205)655-8005

Guard, Slant Top Rub Rails

AT401261

\$2,142.00

Copyright © Deere & Company. All Rights Reserved.

About Our Site | Privacy and Data | Legal | |