

| AARCO PRODUCT # | 2016 List |
|---------------------|-------------|
| OADC4872 | \$ 1,405.11 |
| 120A-23CS | \$ 131.63 |
| 120A-23M | \$ 131.63 |
| 120A-34CS | \$ 267.70 |
| 120A-34M | \$ 267.70 |
| 120A-35CS | \$ 280.71 |
| 120A-35M | \$ 280.71 |
| 120A-410CS | \$ 628.66 |
| 120A-410M | \$ 628.66 |
| 120A-412CS | \$ 714.68 |
| 120A-412M | \$ 714.68 |
| 120A-416C-2S | \$ 1,151.54 |
| 120A-416CS | \$ 958.72 |
| 120A-416M | \$ 958.72 |
| 120A-416M-2 | \$ 1,151.54 |
| 120A-44CS | \$ 325.64 |
| 120A-44M | \$ 325.64 |
| 120A-45CS | \$ 353.15 |
| 120A-45M | \$ 353.15 |
| 120A-46CS | \$ 401.83 |
| 120A-46M | \$ 401.83 |
| 120A-48CS | \$ 527.19 |
| 120A-48M | \$ 527.19 |
| 120C-410C-82CR | \$ 718.27 |
| 120C-410M-82CR | \$ 718.27 |
| 120C-410M-82CR- 703 | \$ 718.27 |
| 120C-410M-82CR-530 | \$ 718.27 |
| 120C-410M-82CR-531 | \$ 718.27 |
| 120C-410M-82CR-679 | \$ 718.27 |
| 120C-410M-82CR-683 | \$ 718.27 |
| 120C-410M-82CR-685 | \$ 718.27 |
| 120C-410M-82CR-700 | \$ 718.27 |
| 120C-410M-82CR-701 | \$ 718.27 |
| 120C-410M-82CR-702 | \$ 718.27 |
| 120C-410M-82CR-704 | \$ 718.27 |
| 120C-410M-82CR-705 | \$ 718.27 |
| 120C-410M-82CR-706 | \$ 718.27 |
| 120C-410M-82CR-802 | \$ 718.27 |
| 120C-410M-82CR-812 | \$ 718.27 |
| 120C-410M-82CR-819 | \$ 718.27 |
| 120C-410M-82CR-831 | \$ 718.27 |
| 120C-410M-82CR-837 | \$ 718.27 |

| | |
|----------------------|-------------|
| 120C-410M-82CR-845 | \$ 718.27 |
| 120C-410M-82CR-854 | \$ 718.27 |
| 120C-410M-82CR-856 | \$ 718.27 |
| 120C-410M-82CR-876 | \$ 718.27 |
| 120C-410M-82CR-878 | \$ 718.27 |
| 120C-412C-84CR | \$ 910.25 |
| 120C-412M-84CR | \$ 910.25 |
| 120C-412M-84CR- 703 | \$ 910.25 |
| 120C-412M-84CR-530 | \$ 910.25 |
| 120C-412M-84CR-531 | \$ 910.25 |
| 120C-412M-84CR-679 | \$ 910.25 |
| 120C-412M-84CR-683 | \$ 910.25 |
| 120C-412M-84CR-685 | \$ 910.25 |
| 120C-412M-84CR-700 | \$ 910.25 |
| 120C-412M-84CR-701 | \$ 910.25 |
| 120C-412M-84CR-702 | \$ 910.25 |
| 120C-412M-84CR-704 | \$ 910.25 |
| 120C-412M-84CR-705 | \$ 910.25 |
| 120C-412M-84CR-706 | \$ 910.25 |
| 120C-412M-84CR-802 | \$ 910.25 |
| 120C-412M-84CR-812 | \$ 910.25 |
| 120C-412M-84CR-819 | \$ 910.25 |
| 120C-412M-84CR-831 | \$ 910.25 |
| 120C-412M-84CR-837 | \$ 910.25 |
| 120C-412M-84CR-845 | \$ 910.25 |
| 120C-412M-84CR-854 | \$ 910.25 |
| 120C-412M-84CR-856 | \$ 910.25 |
| 120C-412M-84CR-876 | \$ 910.25 |
| 120C-416C-124CR | \$ 1,279.87 |
| 120C-416M-124CR | \$ 1,279.87 |
| 120C-416M-124CR- 703 | \$ 1,279.87 |
| 120C-416M-124CR-530 | \$ 1,279.87 |
| 120C-416M-124CR-531 | \$ 1,279.87 |
| 120C-416M-124CR-679 | \$ 1,279.87 |
| 120C-416M-124CR-683 | \$ 1,279.87 |
| 120C-416M-124CR-685 | \$ 1,279.87 |
| 120C-416M-124CR-700 | \$ 1,279.87 |
| 120C-416M-124CR-701 | \$ 1,279.87 |
| 120C-416M-124CR-702 | \$ 1,279.87 |
| 120C-416M-124CR-704 | \$ 1,279.87 |
| 120C-416M-124CR-705 | \$ 1,279.87 |
| 120C-416M-124CR-706 | \$ 1,279.87 |
| 120C-416M-124CR-802 | \$ 1,279.87 |
| 120C-416M-124CR-812 | \$ 1,279.87 |
| 120C-416M-124CR-819 | \$ 1,279.87 |
| 120C-416M-124CR-831 | \$ 1,279.87 |
| 120C-416M-124CR-837 | \$ 1,279.87 |

| | |
|---------------------|-------------|
| 120C-416M-124CR-845 | \$ 1,279.87 |
| 120C-416M-124CR-854 | \$ 1,279.87 |
| 120C-416M-124CR-856 | \$ 1,279.87 |
| 120C-416M-124CR-876 | \$ 1,279.87 |
| 120C-46C-42CR | \$ 485.57 |
| 120C-46M-42CR | \$ 485.57 |
| 120C-46M-42CR- 703 | \$ 485.57 |
| 120C-46M-42CR-530 | \$ 485.57 |
| 120C-46M-42CR-531 | \$ 485.57 |
| 120C-46M-42CR-679 | \$ 485.57 |
| 120C-46M-42CR-683 | \$ 485.57 |
| 120C-46M-42CR-685 | \$ 485.57 |
| 120C-46M-42CR-700 | \$ 485.57 |
| 120C-46M-42CR-701 | \$ 485.57 |
| 120C-46M-42CR-702 | \$ 485.57 |
| 120C-46M-42CR-704 | \$ 485.57 |
| 120C-46M-42CR-705 | \$ 485.57 |
| 120C-46M-42CR-706 | \$ 485.57 |
| 120C-46M-42CR-802 | \$ 485.57 |
| 120C-46M-42CR-812 | \$ 485.57 |
| 120C-46M-42CR-819 | \$ 485.57 |
| 120C-46M-42CR-831 | \$ 485.57 |
| 120C-46M-42CR-837 | \$ 485.57 |
| 120C-46M-42CR-845 | \$ 485.57 |
| 120C-46M-42CR-854 | \$ 485.57 |
| 120C-46M-42CR-856 | \$ 485.57 |
| 120C-46M-42CR-876 | \$ 485.57 |
| 120C-46M-42CR-878 | \$ 485.57 |
| 120C-48C-62CR | \$ 606.83 |
| 120C-48M-62CR | \$ 606.83 |
| 120C-48M-62CR- 703 | \$ 606.83 |
| 120C-48M-62CR-530 | \$ 606.83 |
| 120C-48M-62CR-531 | \$ 606.83 |
| 120C-48M-62CR-679 | \$ 606.83 |
| 120C-48M-62CR-683 | \$ 606.83 |
| 120C-48M-62CR-685 | \$ 606.83 |
| 120C-48M-62CR-700 | \$ 606.83 |
| 120C-48M-62CR-701 | \$ 606.83 |
| 120C-48M-62CR-702 | \$ 606.83 |
| 120C-48M-62CR-704 | \$ 606.83 |
| 120C-48M-62CR-705 | \$ 606.83 |
| 120C-48M-62CR-706 | \$ 606.83 |
| 120C-48M-62CR-802 | \$ 606.83 |
| 120C-48M-62CR-812 | \$ 606.83 |
| 120C-48M-62CR-819 | \$ 606.83 |
| 120C-48M-62CR-831 | \$ 606.83 |
| 120C-48M-62CR-837 | \$ 606.83 |

| | |
|---------------------|-------------|
| 120C-48M-62CR-845 | \$ 606.83 |
| 120C-48M-62CR-854 | \$ 606.83 |
| 120C-48M-62CR-856 | \$ 606.83 |
| 120C-48M-62CR-876 | \$ 606.83 |
| 120C-48M-62CR-878 | \$ 606.83 |
| 120D-410C-262 | \$ 799.92 |
| 120D-410M-262-700 | \$ 799.92 |
| 120D-412C-282 | \$ 912.46 |
| 120D-412M-282-700 | \$ 912.46 |
| 120D-416C-2122 | \$ 1,244.97 |
| 120D-416M-2122-700 | \$ 1,244.97 |
| 120D-48C-242 | \$ 645.45 |
| 120D-48M-242-700 | \$ 645.45 |
| 120E-410C | \$ 788.89 |
| 120E-410C-700 | \$ 788.89 |
| 120E-410M | \$ 788.89 |
| 120E-410M-897 | \$ 788.89 |
| 120E-412C | \$ 959.90 |
| 120E-412C-700 | \$ 959.90 |
| 120E-412M | \$ 959.90 |
| 120E-412M-897 | \$ 959.90 |
| 120E-416C | \$ 1,307.45 |
| 120E-416C-700 | \$ 1,307.45 |
| 120E-416M | \$ 1,307.45 |
| 120E-416M-897 | \$ 1,307.45 |
| 120E-46C | \$ 490.98 |
| 120E-46C-700 | \$ 490.98 |
| 120E-46M | \$ 490.98 |
| 120E-46M-897 | \$ 490.98 |
| 120E-48C | \$ 617.87 |
| 120E-48C-700 | \$ 617.87 |
| 120E-48M | \$ 617.87 |
| 120E-48M-897 | \$ 617.87 |
| 120F-410C-262-700 | \$ 783.37 |
| 120F-410M-262- 703 | \$ 783.37 |
| 120F-410M-262-700 | \$ 783.37 |
| 120F-412C-282-700 | \$ 926.80 |
| 120F-412M-282- 703 | \$ 926.80 |
| 120F-412M-282-700 | \$ 926.80 |
| 120F-416C-2122-700 | \$ 1,290.90 |
| 120F-416M-2122- 703 | \$ 1,290.90 |
| 120F-416M-2122-700 | \$ 1,290.90 |
| 120F-48C-242-700 | \$ 617.87 |
| 120F-48M-242- 703 | \$ 617.87 |
| 120F-48M-242-700 | \$ 617.87 |
| 1-WA-1B | \$ 274.25 |
| 1-WA-1BP | \$ 316.25 |

| | |
|-----------------|-------------|
| 420-007C-3648G | \$ 310.65 |
| 420-007C-48120G | \$ 734.44 |
| 420-007C-48144G | \$ 835.95 |
| 420-007C-48192G | \$ 1,121.55 |
| 420-007C-4848G | \$ 341.71 |
| 420-007C-4872G | \$ 469.99 |
| 420-007C-4896G | \$ 616.63 |
| 420-007M-3648 | \$ 310.65 |
| 420-007M-48120 | \$ 734.44 |
| 420-007M-48144 | \$ 835.95 |
| 420-007M-48192 | \$ 1,121.55 |
| 420-007M-4848 | \$ 341.71 |
| 420-007M-4872 | \$ 469.99 |
| 420-007M-4896 | \$ 616.63 |
| 420OD1824 | \$ 94.07 |
| 420OD2436 | \$ 161.97 |
| 420OD3648 | \$ 327.68 |
| 420OD3660 | \$ 344.12 |
| 420OD48120 | \$ 771.16 |
| 420OD48144 | \$ 877.75 |
| 420OD48192 | \$ 1,177.62 |
| 420OD4848 | \$ 360.58 |
| 420OD4860 | \$ 433.03 |
| 420OD4872 | \$ 493.49 |
| 420OD4896 | \$ 647.45 |
| 420WD1824 | \$ 94.07 |
| 420WD2436 | \$ 161.97 |
| 420WD3648 | \$ 327.68 |
| 420WD3660 | \$ 344.12 |
| 420WD48120 | \$ 771.16 |
| 420WD48144 | \$ 877.75 |
| 420WD48192 | \$ 1,177.62 |
| 420WD4848 | \$ 360.58 |
| 420WD4860 | \$ 433.03 |
| 420WD4872 | \$ 493.49 |
| 420WD4896 | \$ 647.45 |
| 420WWD1824 | \$ 94.07 |
| 420WWD2436 | \$ 161.97 |
| 420WWD3648 | \$ 327.68 |
| 420WWD3660 | \$ 344.12 |
| 420WWD48120 | \$ 771.16 |
| 420WWD48144 | \$ 877.75 |
| 420WWD48192 | \$ 1,177.62 |
| 420WWD4848 | \$ 360.58 |
| 420WWD4860 | \$ 433.03 |
| 420WWD4872 | \$ 493.49 |
| 420WWD4896 | \$ 647.45 |

| | |
|----------|-----------|
| 4-P | \$ 336.09 |
| 4-S | \$ 300.23 |
| A-11 | \$ 164.04 |
| A-1B | \$ 168.04 |
| A-1G | \$ 168.04 |
| A-1P | \$ 212.82 |
| A-1SG | \$ 269.57 |
| A-1SS | \$ 269.57 |
| A-311 | \$ 144.70 |
| A-311SB | \$ 217.48 |
| A-311SG | \$ 217.48 |
| A-311SW | \$ 217.48 |
| A-35 | \$ 138.87 |
| A-35SS | \$ 217.48 |
| A-3B | \$ 149.37 |
| A-3G | \$ 149.37 |
| A-3P | \$ 186.72 |
| A-5 | \$ 157.54 |
| A-5SB | \$ 270.62 |
| A-5SW | \$ 270.62 |
| AA-11 | \$ 257.80 |
| AA-1B | \$ 261.40 |
| AA-1BP | \$ 306.65 |
| AA-1G | \$ 261.40 |
| AA-1SG | \$ 362.93 |
| AA-1SS | \$ 362.93 |
| AA-311 | \$ 225.23 |
| AA-311SB | \$ 334.18 |
| AA-311SG | \$ 334.18 |
| AA-311SW | \$ 334.18 |
| AA-35 | \$ 222.89 |
| AA-35SS | \$ 334.18 |
| AA-3B | \$ 231.06 |
| AA-3BP | \$ 267.13 |
| AA-3G | \$ 231.06 |
| AA-5 | \$ 250.90 |
| AA-5SB | \$ 364.28 |
| AA-5SW | \$ 364.28 |
| AB1824 | \$ 24.47 |
| AB2436 | \$ 35.64 |
| AB3648 | \$ 59.45 |
| ABI08L | \$ 189.05 |
| ABI08S | \$ 105.41 |
| AC1824B | \$ 26.07 |
| AC2436B | \$ 39.09 |
| AC3648B | \$ 63.82 |
| ACB3648B | \$ 580.57 |

| | |
|-------------|-------------|
| ACB4260B | \$ 659.36 |
| ACB4872B | \$ 706.36 |
| ADC2412 | \$ 245.91 |
| ADC2412BA | \$ 295.09 |
| ADC2418 | \$ 283.72 |
| ADC2418BA | \$ 340.45 |
| ADC2418H | \$ 363.04 |
| ADC2418HBA | \$ 435.65 |
| ADC2418HI | \$ 492.12 |
| ADC2418HIBA | \$ 590.55 |
| ADC2418I | \$ 516.03 |
| ADC2418IBA | \$ 619.24 |
| ADC3612 | \$ 291.95 |
| ADC3612BA | \$ 350.34 |
| ADC3624 | \$ 351.35 |
| ADC3624BA | \$ 421.61 |
| ADC3624H | \$ 462.65 |
| ADC3624HBA | \$ 555.18 |
| ADC3624HI | \$ 618.52 |
| ADC3624HIBA | \$ 742.23 |
| ADC3624I | \$ 575.03 |
| ADC3624IBA | \$ 690.03 |
| ADC3630 | \$ 389.94 |
| ADC3630BA | \$ 467.92 |
| ADC3630H | \$ 531.12 |
| ADC3630HBA | \$ 637.35 |
| ADC3630HI | \$ 748.94 |
| ADC3630HIBA | \$ 898.74 |
| ADC3630I | \$ 618.52 |
| ADC3630IBA | \$ 742.23 |
| ADC3636 | \$ 467.92 |
| ADC3636BA | \$ 561.50 |
| ADC3636H | \$ 637.35 |
| ADC3636HBA | \$ 764.81 |
| ADC3636HI | \$ 898.74 |
| ADC3636HIBA | \$ 1,078.48 |
| ADC3636I | \$ 741.38 |
| ADC3636IBA | \$ 890.66 |
| ADC3648 | \$ 528.43 |
| ADC3648BA | \$ 634.11 |
| ADC3648H | \$ 778.53 |
| ADC3648HBA | \$ 934.23 |
| ADC3648HI | \$ 1,066.28 |
| ADC3648HIBA | \$ 1,279.52 |
| ADC3648I | \$ 850.21 |
| ADC3648IBA | \$ 1,020.25 |
| ADC3660 | \$ 642.61 |

| | |
|---------------|-------------|
| ADC3660BA | \$ 771.14 |
| ADC3660H | \$ 876.69 |
| ADC3660HBA | \$ 1,052.01 |
| ADC3660HI | \$ 1,238.38 |
| ADC3660HIBA | \$ 1,486.06 |
| ADC3660I | \$ 969.46 |
| ADC3660IBA | \$ 1,163.35 |
| ADC3672 | \$ 826.94 |
| ADC3672-3 | \$ 919.31 |
| ADC3672-3BA | \$ 1,103.17 |
| ADC3672-3H | \$ 1,164.42 |
| ADC3672-3HBA | \$ 1,397.32 |
| ADC3672-3HI | \$ 1,633.69 |
| ADC3672-3HIBA | \$ 1,960.43 |
| ADC3672-3I | \$ 1,398.05 |
| ADC3672-3IBA | \$ 1,677.66 |
| ADC3672BA | \$ 992.31 |
| ADC3672H | \$ 1,044.76 |
| ADC3672HBA | \$ 1,253.71 |
| ADC3672HI | \$ 1,519.40 |
| ADC3672HIBA | \$ 1,823.28 |
| ADC3672I | \$ 1,536.75 |
| ADC3672IBA | \$ 1,844.08 |
| ADC4836 | \$ 512.29 |
| ADC4836BA | \$ 614.75 |
| ADC4836H | \$ 732.81 |
| ADC4836HBA | \$ 879.37 |
| ADC4836HI | \$ 907.61 |
| ADC4836HIBA | \$ 1,089.13 |
| ADC4836I | \$ 778.53 |
| ADC4836IBA | \$ 934.23 |
| ADC4860 | \$ 795.76 |
| ADC4860BA | \$ 954.92 |
| ADC4860H | \$ 1,082.40 |
| ADC4860HBA | \$ 1,298.88 |
| ADC4860HI | \$ 1,511.33 |
| ADC4860HIBA | \$ 1,813.60 |
| ADC4860I | \$ 1,094.51 |
| ADC4860IBA | \$ 1,313.40 |
| ADC4872 | \$ 1,034.00 |
| ADC4872-3 | \$ 1,123.90 |
| ADC4872-3BA | \$ 1,348.65 |
| ADC4872-3H | \$ 1,452.17 |
| ADC4872-3HBA | \$ 1,742.60 |
| ADC4872-3HI | \$ 1,869.00 |
| ADC4872-3HIBA | \$ 2,242.79 |
| ADC4872-3I | \$ 1,553.83 |

| | |
|---------------|-------------|
| ADC4872-3IBA | \$ 1,864.58 |
| ADC4872BA | \$ 1,240.80 |
| ADC4872H | \$ 1,310.99 |
| ADC4872HBA | \$ 1,573.19 |
| ADC4872HI | \$ 1,718.40 |
| ADC4872HIBA | \$ 2,062.07 |
| ADC4872I | \$ 1,708.99 |
| ADC4872IBA | \$ 2,050.78 |
| ADC4896-3 | \$ 1,317.86 |
| ADC4896-3BA | \$ 1,581.43 |
| ADC4896-3H | \$ 1,747.98 |
| ADC4896-3HBA | \$ 2,097.57 |
| ADC4896-3HI | \$ 2,299.27 |
| ADC4896-3HIBA | \$ 2,759.13 |
| ADC4896-3I | \$ 1,791.89 |
| ADC4896-3IBA | \$ 2,150.26 |
| ADCO2418R | \$ 303.57 |
| ADCO3624R | \$ 375.94 |
| ADCO3630R | \$ 417.23 |
| ADCO3636R | \$ 500.68 |
| ADCO3648R | \$ 565.42 |
| ADCO3660R | \$ 687.60 |
| ADCO4836R | \$ 548.16 |
| ADCW2418R | \$ 303.57 |
| ADCW3624R | \$ 375.94 |
| ADCW3630R | \$ 417.23 |
| ADCW3636R | \$ 500.68 |
| ADCW3648R | \$ 565.42 |
| ADCW3660R | \$ 687.60 |
| ADCW4836R | \$ 548.16 |
| ADCWW2418R | \$ 303.57 |
| ADCWW3624R | \$ 375.94 |
| ADCWW3630R | \$ 417.23 |
| ADCWW3636R | \$ 500.68 |
| ADCWW3648R | \$ 565.42 |
| ADCWW3660R | \$ 687.60 |
| ADCWW4836R | \$ 548.16 |
| AE66 | \$ 68.06 |
| ALS18 | \$ 237.50 |
| ALS18 | \$ 237.50 |
| ALS18 | \$ 237.50 |
| AOFD1218 | \$ 88.46 |
| AOFD1812 | \$ 88.46 |
| AOFD1824 | \$ 118.13 |
| AOFD2418 | \$ 118.13 |
| AOFD2430 | \$ 155.39 |
| AOFD2436 | \$ 181.74 |

| | |
|-----------|-----------|
| AOFD3024 | \$ 155.39 |
| AOFD3036 | \$ 309.61 |
| AOFD3624 | \$ 181.74 |
| AOFD3630 | \$ 309.61 |
| AOFD3648 | \$ 382.95 |
| AOFD3660 | \$ 569.51 |
| AOFD4836 | \$ 382.95 |
| AOFD4872 | \$ 643.89 |
| AOFD4896 | \$ 854.97 |
| AOFD6036 | \$ 569.51 |
| AOFD7248 | \$ 643.89 |
| AOFD9648 | \$ 854.97 |
| APS1824 | \$ 53.46 |
| APS1824M | \$ 58.58 |
| APS2436 | \$ 86.64 |
| APS2436M | \$ 94.28 |
| APS3648 | \$ 142.26 |
| APS3648M | \$ 152.39 |
| APS48120 | \$ 401.87 |
| APS48120M | \$ 427.00 |
| APS48144 | \$ 456.77 |
| APS48144M | \$ 486.92 |
| APS4848 | \$ 177.23 |
| APS4848M | \$ 187.37 |
| APS4860 | \$ 222.62 |
| APS4860M | \$ 235.25 |
| APS4872 | \$ 252.77 |
| APS4872M | \$ 267.91 |
| APS4896 | \$ 326.33 |
| APS4896M | \$ 346.46 |
| APS-50 | \$ 101.75 |
| APS-60 | \$ 120.48 |
| APS-70 | \$ 155.25 |
| APS-84 | \$ 202.39 |
| ARC3648B | \$ 562.60 |
| ARC4260B | \$ 642.77 |
| ARC4872B | \$ 698.06 |
| ARS3648S | \$ 677.33 |
| ARS4260S | \$ 794.83 |
| ARS4872S | \$ 898.50 |
| ATM10L | \$ 176.45 |
| ATM10S | \$ 93.96 |
| AW1824 | \$ 27.19 |
| AW2436 | \$ 40.27 |
| AW3648 | \$ 69.08 |
| BA-11 | \$ 302.73 |
| BA-1B | \$ 305.75 |

| | |
|-------------|-------------|
| BA-1BP | \$ 367.97 |
| BA-1G | \$ 305.75 |
| BA-1SG | \$ 408.45 |
| BA-1SS | \$ 408.45 |
| BA-311 | \$ 264.91 |
| BA-311SB | \$ 360.71 |
| BA-311SG | \$ 360.71 |
| BA-311SW | \$ 360.71 |
| BA-35 | \$ 256.74 |
| BA-35SS | \$ 360.71 |
| BA-3B | \$ 267.24 |
| BA-3BP | \$ 323.26 |
| BA-3G | \$ 267.24 |
| BA-5 | \$ 296.25 |
| BA-5SB | \$ 408.89 |
| BA-5SW | \$ 408.89 |
| BEE06S | \$ 114.58 |
| BEL-101B | \$ 2,271.78 |
| BEL-101B-4P | \$ 2,328.68 |
| BEL-101C | \$ 2,077.05 |
| BEL-101C-4P | \$ 2,243.80 |
| BG24 | \$ 25.79 |
| BG36 | \$ 38.01 |
| BG48 | \$ 47.26 |
| BG72 | \$ 70.57 |
| BM2x2 | \$ 468.81 |
| BM2x2 | \$ 468.81 |
| BM2x2BA | \$ 562.56 |
| BM2x2BA | \$ 562.56 |
| BM2x2EB | \$ 562.56 |
| BM2x2FG | \$ 562.56 |
| BM2x4 | \$ 591.52 |
| BM2x4 | \$ 591.52 |
| BM2x4BA | \$ 709.83 |
| BM2x4BA | \$ 709.83 |
| BM2X4BA | \$ 709.83 |
| BM2x4BK | \$ 709.83 |
| BM2x4EB | \$ 709.83 |
| BM2x4FG | \$ 709.83 |
| BM3343 | \$ 1,368.68 |
| BM3343BA | \$ 1,642.40 |
| BM3343EB | \$ 1,642.40 |
| BM3343FG | \$ 1,642.40 |
| BM3647 | \$ 1,503.96 |
| BM3647BA | \$ 1,804.76 |
| BM3647EB | \$ 1,804.76 |
| BM3647FG | \$ 1,804.76 |

| | |
|-----------|-------------|
| BM4260 | \$ 1,884.67 |
| BM4260BA | \$ 2,261.61 |
| BM4260EB | \$ 2,261.61 |
| BM4260FG | \$ 2,261.61 |
| BOC1218NT | \$ 25.98 |
| BOC1824NT | \$ 36.31 |
| BOC2436NT | \$ 65.56 |
| BOC3648NT | \$ 94.71 |
| BOC3660NT | \$ 171.48 |
| BOFD1218 | \$ 84.24 |
| BOFD1812 | \$ 84.24 |
| BOFD1824 | \$ 112.36 |
| BOFD2418 | \$ 112.36 |
| BOFD2430 | \$ 147.99 |
| BOFD2436 | \$ 171.14 |
| BOFD3024 | \$ 147.99 |
| BOFD3036 | \$ 292.09 |
| BOFD3624 | \$ 171.14 |
| BOFD3630 | \$ 292.09 |
| BOFD3648 | \$ 357.16 |
| BOFD3660 | \$ 532.24 |
| BOFD4836 | \$ 357.16 |
| BOFD4872 | \$ 602.73 |
| BOFD4896 | \$ 788.75 |
| BOFD6036 | \$ 532.24 |
| BOFD7248 | \$ 602.73 |
| BOFD9648 | \$ 788.75 |
| BPH1BK | \$ 276.04 |
| BPH1S | \$ 287.37 |
| C44 | \$ 46.62 |
| C44A | \$ 27.91 |
| CBC2418R | \$ 223.79 |
| CBC2418RH | \$ 273.95 |
| CBC2418S | \$ 257.23 |
| CBC2418S | \$ 257.23 |
| CBC2424S | \$ 333.23 |
| CBC2424S | \$ 333.23 |
| CBC3624R | \$ 261.09 |
| CBC3624RC | \$ 304.82 |
| CBC3624RH | \$ 335.69 |
| CBC3624S | \$ 403.38 |
| CBC3624S | \$ 403.38 |
| CBC3630R | \$ 315.11 |
| CBC3630RH | \$ 501.59 |
| CBC3636R | \$ 378.13 |
| CBC3636RH | \$ 601.92 |
| CBC3648R | \$ 458.38 |

| | |
|-------------|-------------|
| CBC3648RC | \$ 533.76 |
| CBC3648RH | \$ 625.06 |
| CBC3648S | \$ 549.54 |
| CBC3648S | \$ 549.54 |
| CBC3660R | \$ 578.25 |
| CBC3660RC | \$ 675.23 |
| CBC3660RH | \$ 713.81 |
| CBC3672-3R | \$ 733.27 |
| CBC3672-3RH | \$ 904.15 |
| CBC3672R | \$ 669.51 |
| CBC3672RC | \$ 870.72 |
| CBC3672RH | \$ 816.71 |
| CBC4836R | \$ 430.60 |
| CBC4836RH | \$ 580.05 |
| CBC4860R | \$ 739.65 |
| CBC4860RH | \$ 767.05 |
| CBC4872-3R | \$ 842.40 |
| CBC4872-3RH | \$ 1,023.77 |
| CBC4872R | \$ 785.14 |
| CBC4872RC | \$ 999.97 |
| CBC4872RH | \$ 917.66 |
| CBC4896-3R | \$ 947.51 |
| CBC4896-3RH | \$ 1,246.27 |
| CBC4896RC | \$ 1,130.52 |
| CCS-12 | \$ 13.87 |
| CCS-12 | \$ 13.46 |
| CCS-12 | \$ 13.46 |
| CCS144 | \$ 154.68 |
| CDC2418 | \$ 290.81 |
| CDC2418H | \$ 396.73 |
| CDC3624 | \$ 343.35 |
| CDC3624H | \$ 501.59 |
| CDC3630 | \$ 378.17 |
| CDC3630H | \$ 571.05 |
| CDC3636 | \$ 453.81 |
| CDC3636H | \$ 685.26 |
| CDC3648 | \$ 569.51 |
| CDC3648H | \$ 861.45 |
| CDC3660 | \$ 687.12 |
| CDC3660H | \$ 1,014.84 |
| CDC3672 | \$ 916.50 |
| CDC3672-3 | \$ 1,029.38 |
| CDC3672-3H | \$ 1,424.33 |
| CDC3672H | \$ 1,299.90 |
| CDC4836 | \$ 552.86 |
| CDC4836H | \$ 769.12 |
| CDC4860 | \$ 844.73 |

| | |
|------------|-------------|
| CDC4860H | \$ 1,117.45 |
| CDC4872 | \$ 1,212.91 |
| CDC4872-3 | \$ 1,113.19 |
| CDC4872-3H | \$ 1,509.15 |
| CDC4872H | \$ 1,653.27 |
| CDC4896-3 | \$ 1,194.44 |
| CDC4896-3H | \$ 1,659.14 |
| CER07S | \$ 105.41 |
| CHI09L | \$ 176.45 |
| CLS | \$ 78.20 |
| CMD1418 | \$ 257.27 |
| CO2436B | \$ 81.25 |
| CO3648B | \$ 120.99 |
| CO4872B | \$ 212.23 |
| CO4896B | \$ 282.96 |
| COF03L | \$ 176.45 |
| CTS | \$ 73.79 |
| DB1824 | \$ 25.94 |
| DB2436 | \$ 39.50 |
| DB3648 | \$ 81.53 |
| DB3660 | \$ 124.55 |
| DB48120 | \$ 271.83 |
| DB48144 | \$ 321.65 |
| DB4848 | \$ 254.82 |
| DB4860 | \$ 150.09 |
| DB4872 | \$ 183.47 |
| DB4896 | \$ 254.83 |
| DBM3343 | \$ 2,467.35 |
| DBM3343BA | \$ 2,960.81 |
| DBM3343EB | \$ 2,960.81 |
| DBM3343FG | \$ 2,960.81 |
| DBM3647 | \$ 2,682.48 |
| DBM3647BA | \$ 3,218.97 |
| DBM3647EB | \$ 3,218.97 |
| DBM3647FG | \$ 3,218.97 |
| DBM4260 | \$ 3,354.78 |
| DBM4260BA | \$ 4,025.73 |
| DBM4260EB | \$ 4,025.73 |
| DBM4260FG | \$ 4,025.73 |
| DBO1824 | \$ 57.90 |
| DBO2436 | \$ 111.92 |
| DBO3648 | \$ 180.11 |
| DBO3660 | \$ 227.70 |
| DBO48120 | \$ 443.84 |
| DBO48144 | \$ 501.73 |
| DBO4848 | \$ 222.56 |
| DBO4860 | \$ 263.73 |

| | |
|--------------|-----------|
| DBO4872 | \$ 289.46 |
| DBO4896 | \$ 379.52 |
| DBW1824 | \$ 57.90 |
| DBW2436 | \$ 111.91 |
| DBW3648 | \$ 180.11 |
| DBW3660 | \$ 227.70 |
| DBW48120 | \$ 443.84 |
| DBW48144 | \$ 501.73 |
| DBW4848 | \$ 222.56 |
| DBW4860 | \$ 263.73 |
| DBW4872 | \$ 289.46 |
| DBW4896 | \$ 379.52 |
| DBWW1824 | \$ 57.90 |
| DBWW2436 | \$ 111.92 |
| DBWW3648 | \$ 180.11 |
| DBWW3660 | \$ 227.70 |
| DBWW48120 | \$ 443.84 |
| DBWW48144 | \$ 501.73 |
| DBWW4848 | \$ 222.56 |
| DBWW4860 | \$ 263.73 |
| DBWW4872 | \$ 289.46 |
| DBWW4896 | \$ 379.52 |
| DC1824G | \$ 28.47 |
| DC2436G | \$ 42.83 |
| DC3648G | \$ 77.55 |
| DC3660G | \$ 144.71 |
| DC48120G | \$ 318.96 |
| DC48144G | \$ 383.49 |
| DC4860G | \$ 180.71 |
| DC4872G | \$ 198.11 |
| DC4896G | \$ 247.19 |
| DCC2412R | \$ 184.89 |
| DCC2412RBA | \$ 221.88 |
| DCC2412RR | \$ 221.88 |
| DCC2418R | \$ 213.25 |
| DCC2418RBA | \$ 255.91 |
| DCC2418RH | \$ 353.78 |
| DCC2418RHBA | \$ 424.53 |
| DCC2418RHI | \$ 427.59 |
| DCC2418RHIBA | \$ 513.10 |
| DCC2418RI | \$ 338.84 |
| DCC2418RIBA | \$ 406.60 |
| DCC2418RR | \$ 255.91 |
| DCC3612R | \$ 219.51 |
| DCC3612RBA | \$ 263.41 |
| DCC3612RR | \$ 263.41 |
| DCC3624R | \$ 275.45 |

| | |
|--------------|-------------|
| DCC3624RBA | \$ 330.53 |
| DCC3624RH | \$ 411.22 |
| DCC3624RHBA | \$ 493.46 |
| DCC3624RHI | \$ 584.91 |
| DCC3624RHIBA | \$ 701.88 |
| DCC3624RI | \$ 463.96 |
| DCC3624RIBA | \$ 556.75 |
| DCC3624RR | \$ 330.53 |
| DCC3630R | \$ 326.36 |
| DCC3630RBA | \$ 391.63 |
| DCC3630RH | \$ 463.43 |
| DCC3630RHBA | \$ 556.11 |
| DCC3630RHI | \$ 654.81 |
| DCC3630RHIBA | \$ 785.78 |
| DCC3630RI | \$ 531.12 |
| DCC3630RIBA | \$ 637.35 |
| DCC3630RR | \$ 391.63 |
| DCC3636R | \$ 391.63 |
| DCC3636RBA | \$ 469.96 |
| DCC3636RH | \$ 556.11 |
| DCC3636RHBA | \$ 667.34 |
| DCC3636RHI | \$ 785.78 |
| DCC3636RHIBA | \$ 942.94 |
| DCC3636RI | \$ 637.35 |
| DCC3636RIBA | \$ 764.81 |
| DCC3636RR | \$ 469.96 |
| DCC3648R | \$ 468.81 |
| DCC3648RBA | \$ 562.57 |
| DCC3648RH | \$ 665.78 |
| DCC3648RHBA | \$ 798.93 |
| DCC3648RHI | \$ 1,007.10 |
| DCC3648RHIBA | \$ 1,208.52 |
| DCC3648RI | \$ 812.96 |
| DCC3648RIBA | \$ 975.55 |
| DCC3648RR | \$ 562.57 |
| DCC3660R | \$ 563.20 |
| DCC3660RBA | \$ 675.85 |
| DCC3660RH | \$ 776.74 |
| DCC3660RHBA | \$ 932.09 |
| DCC3660RHI | \$ 1,095.85 |
| DCC3660RHIBA | \$ 1,315.02 |
| DCC3660RI | \$ 966.68 |
| DCC3660RIBA | \$ 1,160.03 |
| DCC3660RR | \$ 675.85 |
| DCC3672-3R | \$ 691.89 |
| DCC3672-3RBA | \$ 830.26 |
| DCC3672-3RH | \$ 959.50 |

| | |
|----------------|-------------|
| DCC3672-3RHBA | \$ 1,151.39 |
| DCC3672-3RHI | \$ 1,479.06 |
| DCC3672-3RHIBA | \$ 1,774.88 |
| DCC3672-3RI | \$ 1,232.60 |
| DCC3672-3RIBA | \$ 1,479.11 |
| DCC3672-3RR | \$ 830.26 |
| DCC3672R | \$ 678.83 |
| DCC3672RBA | \$ 814.59 |
| DCC3672RH | \$ 928.17 |
| DCC3672RHBA | \$ 1,113.80 |
| DCC3672RHI | \$ 1,331.16 |
| DCC3672RHIBA | \$ 1,597.38 |
| DCC3672RI | \$ 1,117.91 |
| DCC3672RIBA | \$ 1,341.50 |
| DCC3672RR | \$ 814.59 |
| DCC4836R | \$ 462.52 |
| DCC4836RBA | \$ 555.02 |
| DCC4836RH | \$ 633.13 |
| DCC4836RHBA | \$ 759.76 |
| DCC4836RHI | \$ 946.60 |
| DCC4836RHIBA | \$ 1,135.93 |
| DCC4836RI | \$ 705.91 |
| DCC4836RIBA | \$ 847.11 |
| DCC4836RR | \$ 555.02 |
| DCC4860R | \$ 672.30 |
| DCC4860RBA | \$ 806.76 |
| DCC4860RH | \$ 886.39 |
| DCC4860RHBA | \$ 1,063.67 |
| DCC4860RHI | \$ 1,243.76 |
| DCC4860RHIBA | \$ 1,492.51 |
| DCC4860RI | \$ 1,325.39 |
| DCC4860RIBA | \$ 1,590.47 |
| DCC4860RR | \$ 806.76 |
| DCC4872-3R | \$ 861.23 |
| DCC4872-3RBA | \$ 1,033.47 |
| DCC4872-3RH | \$ 1,096.57 |
| DCC4872-3RHBA | \$ 1,315.88 |
| DCC4872-3RHI | \$ 1,690.17 |
| DCC4872-3RHIBA | \$ 2,028.20 |
| DCC4872-3RI | \$ 1,538.67 |
| DCC4872-3RIBA | \$ 1,846.40 |
| DCC4872-3RR | \$ 1,033.47 |
| DCC4872R | \$ 847.22 |
| DCC4872RBA | \$ 1,016.67 |
| DCC4872RH | \$ 998.66 |
| DCC4872RHBA | \$ 1,198.39 |
| DCC4872RHI | \$ 1,586.63 |

| | |
|----------------|-------------|
| DCC4872RHIBA | \$ 1,903.95 |
| DCC4872RI | \$ 1,549.60 |
| DCC4872RIBA | \$ 1,859.54 |
| DCC4872RR | \$ 1,016.67 |
| DCC4896-3R | \$ 1,099.18 |
| DCC4896-3RBA | \$ 1,319.02 |
| DCC4896-3RH | \$ 1,370.71 |
| DCC4896-3RHBA | \$ 1,644.85 |
| DCC4896-3RHI | \$ 1,938.91 |
| DCC4896-3RHIBA | \$ 2,326.70 |
| DCC4896-3RI | \$ 1,745.02 |
| DCC4896-3RIBA | \$ 2,094.03 |
| DCC4896-3RR | \$ 1,319.02 |
| DCCO2418R | \$ 234.98 |
| DCCO3624R | \$ 295.03 |
| DCCO3630R | \$ 375.31 |
| DCCO3636R | \$ 450.38 |
| DCCO3648R | \$ 539.14 |
| DCCO3660R | \$ 647.68 |
| DCCO4836R | \$ 531.89 |
| DCCW2418R | \$ 234.98 |
| DCCW3624R | \$ 295.03 |
| DCCW3630R | \$ 375.31 |
| DCCW3636R | \$ 450.38 |
| DCCW3648R | \$ 539.14 |
| DCCW3660R | \$ 647.68 |
| DCCW4836R | \$ 531.89 |
| DCCWW2418R | \$ 234.98 |
| DCCWW3624R | \$ 295.03 |
| DCCWW3630R | \$ 375.31 |
| DCCWW3636R | \$ 450.38 |
| DCCWW3648R | \$ 539.14 |
| DCCWW3660R | \$ 647.68 |
| DCCWW4836R | \$ 531.89 |
| DCO2436B | \$ 97.07 |
| DCO2436G | \$ 97.07 |
| DCO3648B | \$ 145.11 |
| DCO3648G | \$ 145.11 |
| DCO4872B | \$ 282.88 |
| DCO4872G | \$ 282.88 |
| DCO4896B | \$ 377.00 |
| DCO4896G | \$ 377.00 |
| DF1218014 | \$ 21.21 |
| DF1824014 | \$ 36.89 |
| DF2436014 | \$ 54.78 |
| DF3648014 | \$ 110.85 |
| DF48120014 | \$ 369.49 |

| | |
|-------------|-------------|
| DF48144014 | \$ 443.39 |
| DF4848014 | \$ 147.80 |
| DF4872014 | \$ 221.70 |
| DF4896014 | \$ 295.59 |
| DMBM5272 | \$ 5,169.32 |
| DMBM5272BA | \$ 6,203.20 |
| DMBM5272EB | \$ 6,203.20 |
| DMBM5272FG | \$ 6,203.20 |
| DMBS5286 | \$ 5,908.18 |
| DMBS5286BA | \$ 7,089.81 |
| DMBS5286EB | \$ 7,089.81 |
| DMBS5286FG | \$ 7,089.81 |
| DPP | \$ 365.65 |
| DR2-144 | \$ 111.03 |
| DR2-192 | \$ 147.80 |
| DR2-72 | \$ 56.68 |
| DR2-96 | \$ 74.26 |
| DRC1824TAN | \$ 54.33 |
| DRC2436TAN | \$ 79.67 |
| DRC3648TAN | \$ 123.82 |
| DRC48120TAN | \$ 329.60 |
| DRC48144TAN | \$ 409.94 |
| DRC4848TAN | \$ 165.53 |
| DRC4872TAN | \$ 230.42 |
| DRC4896TAN | \$ 274.62 |
| DS1824G | \$ 73.31 |
| DS2436G | \$ 137.94 |
| DS3648G | \$ 235.79 |
| DS3660G | \$ 329.93 |
| DS48120G | \$ 665.75 |
| DS48144G | \$ 778.87 |
| DS48192G | \$ 1,231.34 |
| DS4860G | \$ 404.16 |
| DS4872G | \$ 448.55 |
| DS4896G | \$ 593.88 |
| DSN1185 | \$ 30.98 |
| DSN1411 | \$ 40.32 |
| DSN2228 | \$ 78.16 |
| DV1218700 | \$ 17.66 |
| DV1824700 | \$ 30.74 |
| DV2436700 | \$ 54.91 |
| DV3648700 | \$ 84.77 |
| DV3660700 | \$ 163.71 |
| DV48120700 | \$ 316.23 |
| DV48144700 | \$ 375.81 |
| DV4848700 | \$ 152.77 |
| DV4860700 | \$ 163.71 |

| | |
|------------|-----------|
| DV4872700 | \$ 181.26 |
| DV4896700 | \$ 236.78 |
| DW2436 | \$ 113.80 |
| DW3648 | \$ 209.05 |
| DW48120166 | \$ 640.77 |
| DW48144166 | \$ 762.00 |
| DW48192166 | \$ 995.79 |
| DW4848 | \$ 277.09 |
| DW4872166 | \$ 395.84 |
| DW4896166 | \$ 518.31 |
| E1 | \$ 4.54 |
| E1 | \$ 4.41 |
| E2 | \$ 2.27 |
| E2 | \$ 2.20 |
| EB1218 | \$ 12.47 |
| EB1824 | \$ 19.19 |
| EB2436 | \$ 27.05 |
| EB3648 | \$ 45.78 |
| EBC1812 | \$ 134.81 |
| EBC2418 | \$ 169.35 |
| EBC3624 | \$ 255.82 |
| EBC3630 | \$ 307.48 |
| EC1218B | \$ 13.36 |
| EC1824B | \$ 22.41 |
| EC2436B | \$ 33.08 |
| EC3648B | \$ 59.33 |
| EDC1812 | \$ 162.80 |
| EDC2418 | \$ 197.33 |
| EDC3624 | \$ 286.10 |
| EDC3630 | \$ 342.02 |
| EFC1824 | \$ 81.69 |
| EFC2436 | \$ 94.42 |
| EFC3648 | \$ 162.32 |
| EFC4848 | \$ 218.93 |
| EFC4860 | \$ 262.04 |
| EFC4872 | \$ 306.60 |
| EFC4896 | \$ 391.47 |
| ER1824 | \$ 29.81 |
| ER2436 | \$ 45.43 |
| ER3648 | \$ 93.78 |
| ER4848 | \$ 152.77 |
| ER4872 | \$ 210.99 |
| ER4896 | \$ 293.05 |
| ERP1824 | \$ 81.09 |
| ERP2436 | \$ 142.03 |
| ERP3648 | \$ 259.58 |
| ERP4848 | \$ 354.25 |

| | |
|-------------|-------------|
| ERP4872 | \$ 449.10 |
| ERP4896 | \$ 529.69 |
| ERP1824 | \$ 81.09 |
| ERP2436 | \$ 142.03 |
| ERP3648 | \$ 259.58 |
| ERP4848 | \$ 354.25 |
| ERP4872 | \$ 449.10 |
| ERP4896 | \$ 529.69 |
| ERV1824700 | \$ 35.36 |
| ERV2436700 | \$ 63.14 |
| ERV3648700 | \$ 97.49 |
| ERV4848700 | \$ 175.69 |
| ERV4872700 | \$ 208.45 |
| ERV4896700 | \$ 272.29 |
| ES-1 | \$ 4.88 |
| ES-2 | \$ 5.22 |
| ES-3 | \$ 5.22 |
| EW1218 | \$ 13.11 |
| EW1824 | \$ 21.99 |
| EW2436 | \$ 32.47 |
| EW3648 | \$ 58.23 |
| EXB10 | \$ 56.65 |
| EXB6 | \$ 22.72 |
| EXB6S | \$ 47.20 |
| F5.0 | \$ 276.86 |
| FAT18 | \$ 1,512.42 |
| FB-1B | \$ 861.50 |
| FB-1C | \$ 731.69 |
| FCO1824G | \$ 55.20 |
| FCO2436G | \$ 81.95 |
| FCO3648G | \$ 124.26 |
| FCO4872G | \$ 220.12 |
| FDCO1824H | \$ 72.04 |
| FDCO2436H | \$ 101.60 |
| FDCO3648H | \$ 154.05 |
| FDCO4872H | \$ 261.94 |
| FE1BK | \$ 317.46 |
| FFVSU144-2 | \$ 6,773.45 |
| FFVSU144-2C | \$ 6,773.45 |
| FFVSU192-2 | \$ 9,031.27 |
| FFVSU192-2C | \$ 9,031.27 |
| FFVSU96-2 | \$ 5,423.52 |
| FFVSU96-2C | \$ 5,423.52 |
| FH-1 | \$ 7.95 |
| FH-2 | \$ 9.16 |
| FMD3624 | \$ 704.78 |
| FMD3630 | \$ 783.95 |

| | |
|-----------|-------------|
| FOS-1 | \$ 83.81 |
| FOS-2 | \$ 83.81 |
| FRE11M | \$ 116.70 |
| GC1204848 | \$ 549.06 |
| GF.75 | \$ 28.33 |
| GF1.0 | \$ 33.92 |
| GFD.75 | \$ 53.25 |
| GFD1.0 | \$ 63.76 |
| HB-10 | \$ 185.28 |
| HB-27 | \$ 261.99 |
| HB-7 | \$ 174.66 |
| HBK-10 | \$ 166.40 |
| HBK-27 | \$ 230.13 |
| HBK-7 | \$ 155.78 |
| HC-1 | \$ 15.47 |
| HC-10 | \$ 175.83 |
| HC-2 | \$ 20.35 |
| HC-27 | \$ 247.83 |
| HC-7 | \$ 165.22 |
| HF.50 | \$ 25.32 |
| HF.75 | \$ 28.33 |
| HF1.0 | \$ 33.92 |
| HF1.5 | \$ 50.63 |
| HF2.0 | \$ 92.05 |
| HFD.50 | \$ 47.59 |
| HFD.75 | \$ 53.25 |
| HFD1.0 | \$ 63.76 |
| HFD1.5 | \$ 95.17 |
| HFD2.0 | \$ 173.05 |
| HS-10 | \$ 185.28 |
| HS-27 | \$ 261.99 |
| HS-7 | \$ 174.66 |
| HSF1114B | \$ 102.09 |
| HSF1114BK | \$ 88.22 |
| HSF1114C | \$ 94.87 |
| HSF1114S | \$ 102.09 |
| HSF811B | \$ 84.90 |
| HSF811BK | \$ 71.84 |
| HSF811C | \$ 78.15 |
| HSF811S | \$ 84.90 |
| HSU412-2 | \$ 3,239.60 |
| HSU412-2C | \$ 3,239.60 |
| HSU412-3 | \$ 4,958.51 |
| HSU412-3C | \$ 4,958.51 |
| HSU412-4 | \$ 5,209.96 |
| HSU412-4C | \$ 5,209.96 |
| HSU416-2 | \$ 4,367.81 |

| | |
|---------------|-------------|
| HSU416-2C | \$ 4,367.81 |
| HSU416-3 | \$ 5,791.37 |
| HSU416-3C | \$ 5,791.37 |
| HSU416-4 | \$ 6,604.26 |
| HSU416-4C | \$ 6,604.26 |
| HSU48-2 | \$ 2,557.08 |
| HSU48-2C | \$ 2,557.08 |
| HSU48-3 | \$ 3,832.97 |
| HSU48-3C | \$ 3,832.97 |
| HSU48-4 | \$ 4,101.72 |
| HSU48-4C | \$ 4,101.72 |
| HT-1B | \$ 672.68 |
| HT-2B | \$ 601.87 |
| ICE13L | \$ 158.07 |
| LB-7 | \$ 163.05 |
| LC-1B | \$ 879.21 |
| LC-1B-4P | \$ 936.77 |
| LC-1C | \$ 755.29 |
| LC-1C-4P | \$ 815.83 |
| LC-2B | \$ 896.91 |
| LC-2B-4P | \$ 949.51 |
| LC-2C | \$ 767.09 |
| LC-2C-4P | \$ 822.20 |
| LC-3B | \$ 2,296.85 |
| LC-3B-4P | \$ 2,349.89 |
| LC-3C | \$ 2,178.03 |
| LC-3C-4P | \$ 2,231.07 |
| LC-3S | \$ 2,360.50 |
| LC-3S-4P | \$ 2,413.55 |
| LC-7 | \$ 155.62 |
| LF-1 | \$ 280.71 |
| LF-2 | \$ 113.43 |
| LG24 | \$ 24.43 |
| LG36 | \$ 35.97 |
| LG48 | \$ 44.52 |
| LG72 | \$ 66.51 |
| LODCC2412R | \$ 326.73 |
| LODCC2412RBA | \$ 378.08 |
| LODCC2412RH | \$ 336.52 |
| LODCC2412RHBA | \$ 389.42 |
| LODCC2418R | \$ 343.39 |
| LODCC2418RBA | \$ 398.08 |
| LODCC2418RH | \$ 353.68 |
| LODCC2418RHBA | \$ 410.01 |
| LODCC3612R | \$ 382.45 |
| LODCC3612RBA | \$ 443.42 |
| LODCC3612RH | \$ 393.92 |

| | |
|-----------------|-------------|
| LODCC3612RHBA | \$ 456.72 |
| LODCC3624R | \$ 425.97 |
| LODCC3624RBA | \$ 495.65 |
| LODCC3624RH | \$ 438.75 |
| LODCC3624RHBA | \$ 510.51 |
| LODCC3648R | \$ 662.15 |
| LODCC3648RBA | \$ 813.38 |
| LODCC3648RH | \$ 682.00 |
| LODCC3648RHBA | \$ 837.78 |
| LODCC3660R | \$ 815.57 |
| LODCC3660RBA | \$ 960.10 |
| LODCC3660RH | \$ 840.03 |
| LODCC3660RHBA | \$ 988.89 |
| LODCC3672-3R | \$ 1,024.16 |
| LODCC3672-3RBA | \$ 1,208.88 |
| LODCC3672-3RH | \$ 1,054.87 |
| LODCC3672-3RHBA | \$ 1,245.14 |
| LOT04S | \$ 114.58 |
| LOWFC2418 | \$ 357.85 |
| LOWFC2418G | \$ 376.86 |
| LOWFC2418LB | \$ 376.86 |
| LOWFC3624 | \$ 450.27 |
| LOWFC3624G | \$ 479.49 |
| LOWFC3624LB | \$ 479.49 |
| LOWFC3648 | \$ 726.46 |
| LOWFC3648G | \$ 757.20 |
| LOWFC3648LB | \$ 757.20 |
| LRC100 | \$ 40.56 |
| LRC101 | \$ 288.87 |
| LRC102 | \$ 188.19 |
| LRC103 | \$ 217.74 |
| LRC104 | \$ 199.53 |
| LRC106 | \$ 213.36 |
| LRC107 | \$ 277.91 |
| LRC108 | \$ 181.64 |
| LRC109 | \$ 310.75 |
| LRC110 | \$ 317.32 |
| LRC111 | \$ 323.88 |
| LRC112 | \$ 196.94 |
| LRC113 | \$ 138.97 |
| LRC114 | \$ 270.27 |
| LRC115 | \$ 273.55 |
| LRC116 | \$ 28.97 |
| LRC117 | \$ 382.32 |
| LRC120 | \$ 214.98 |
| LRC121 | \$ 105.55 |
| LS-7 | \$ 158.90 |

| | |
|--------------|-------------|
| LWL2418C | \$ 362.53 |
| LWL2418O | \$ 362.53 |
| LWL2418W | \$ 362.53 |
| LWL3624C | \$ 450.36 |
| LWL3624O | \$ 450.36 |
| LWL3624W | \$ 450.36 |
| LWL4836C | \$ 688.97 |
| LWL4836O | \$ 688.97 |
| LWL4836W | \$ 688.97 |
| M-4 | \$ 11.74 |
| M-4 | \$ 11.74 |
| M-4 | \$ 11.40 |
| MA-11 | \$ 175.05 |
| MA-1B | \$ 178.23 |
| MA-1G | \$ 178.23 |
| MA-1P | \$ 243.90 |
| MA-1SG | \$ 287.50 |
| MA-1SS | \$ 287.50 |
| MA-311 | \$ 153.83 |
| MA-311SB | \$ 230.22 |
| MA-311SG | \$ 230.22 |
| MA-311SW | \$ 230.22 |
| MA-35 | \$ 157.54 |
| MA-35SS | \$ 230.22 |
| MA-3B | \$ 157.01 |
| MA-3G | \$ 157.01 |
| MA-3P | \$ 214.73 |
| MA-5 | \$ 179.72 |
| MA-5SB | \$ 288.56 |
| MA-5SW | \$ 288.56 |
| MBM5070 | \$ 3,428.73 |
| MBM5070BA | \$ 4,110.97 |
| MBM5070EB | \$ 4,110.97 |
| MBM5070FG | \$ 4,110.97 |
| MBS5084 | \$ 4,033.80 |
| MBS5084BA | \$ 4,840.56 |
| MBS5084EB | \$ 4,840.56 |
| MBS5084FG | \$ 4,840.56 |
| MC-1 | \$ 913.16 |
| MC-2 | \$ 1,067.49 |
| MD-1 | \$ 704.94 |
| MD-2 | \$ 681.21 |
| MFL-2W | \$ 11.40 |
| MFL-6 | \$ 30.81 |
| MMLED4060RBA | \$ 6,774.91 |
| MMLED4872RBA | \$ 8,031.54 |
| MP-36 | \$ 417.29 |

| | |
|--------------|-------------|
| MP-40 | \$ 556.39 |
| MP-48 | \$ 642.11 |
| MPS-50 | \$ 454.35 |
| MPS-70 | \$ 610.13 |
| MPS-84 | \$ 701.01 |
| MR1-72-6 | \$ 122.02 |
| MR1-96-6 | \$ 161.56 |
| MR2-72-6 | \$ 175.89 |
| MR2-96-6 | \$ 234.52 |
| MS1204872 | \$ 690.43 |
| MSC2418H | \$ 485.40 |
| MSC3624H | \$ 638.69 |
| MSC4836H | \$ 1,005.75 |
| MVC-1 | \$ 1,430.19 |
| MVC-2 | \$ 1,841.74 |
| MW-1 | \$ 9.16 |
| MW-2 | \$ 9.64 |
| OADC2412 | \$ 292.63 |
| OADC2412BA | \$ 351.16 |
| OADC2418 | \$ 337.50 |
| OADC2418BA | \$ 405.00 |
| OADC2418H | \$ 442.36 |
| OADC2418HBA | \$ 530.85 |
| OADC2418HI | \$ 497.51 |
| OADC2418HIBA | \$ 597.00 |
| OADC2418I | \$ 470.62 |
| OADC2418IBA | \$ 564.73 |
| OADC3612 | \$ 347.42 |
| OADC3612BA | \$ 416.91 |
| OADC3624 | \$ 397.47 |
| OADC3624BA | \$ 476.96 |
| OADC3624H | \$ 581.94 |
| OADC3624HBA | \$ 698.33 |
| OADC3624HI | \$ 658.86 |
| OADC3624HIBA | \$ 790.62 |
| OADC3624I | \$ 627.93 |
| OADC3624IBA | \$ 753.51 |
| OADC3630 | \$ 432.96 |
| OADC3630BA | \$ 519.56 |
| OADC3630H | \$ 625.24 |
| OADC3630HBA | \$ 750.29 |
| OADC3630HI | \$ 841.72 |
| OADC3630HIBA | \$ 1,010.06 |
| OADC3630I | \$ 793.32 |
| OADC3630IBA | \$ 951.98 |
| OADC3636 | \$ 519.56 |
| OADC3636BA | \$ 623.47 |

| | |
|----------------|-------------|
| OADC3636H | \$ 750.29 |
| OADC3636HBA | \$ 900.34 |
| OADC3636HI | \$ 1,010.06 |
| OADC3636HIBA | \$ 1,212.08 |
| OADC3636I | \$ 951.98 |
| OADC3636IBA | \$ 1,142.37 |
| OADC3648 | \$ 679.02 |
| OADC3648BA | \$ 814.82 |
| OADC3648H | \$ 934.50 |
| OADC3648HBA | \$ 1,121.40 |
| OADC3648HI | \$ 1,196.71 |
| OADC3648HIBA | \$ 1,436.03 |
| OADC3648I | \$ 1,142.92 |
| OADC3648IBA | \$ 1,371.50 |
| OADC3660 | \$ 796.00 |
| OADC3660BA | \$ 955.21 |
| OADC3660H | \$ 1,068.96 |
| OADC3660HBA | \$ 1,282.76 |
| OADC3660HI | \$ 1,337.88 |
| OADC3660HIBA | \$ 1,605.46 |
| OADC3660I | \$ 1,277.38 |
| OADC3660IBA | \$ 1,532.84 |
| OADC3672 | \$ 1,157.70 |
| OADC3672-3 | \$ 1,034.00 |
| OADC3672-3BA | \$ 1,240.80 |
| OADC3672-3H | \$ 1,358.06 |
| OADC3672-3HBA | \$ 1,629.66 |
| OADC3672-3HI | \$ 1,647.13 |
| OADC3672-3HIBA | \$ 1,976.57 |
| OADC3672-3I | \$ 1,579.91 |
| OADC3672-3IBA | \$ 1,895.89 |
| OADC3672BA | \$ 1,389.24 |
| OADC3672H | \$ 1,222.24 |
| OADC3672HBA | \$ 1,466.69 |
| OADC3672HI | \$ 1,482.43 |
| OADC3672HIBA | \$ 1,778.91 |
| OADC3672I | \$ 1,411.84 |
| OADC3672IBA | \$ 1,694.19 |
| OADC4836 | \$ 633.31 |
| OADC4836BA | \$ 759.97 |
| OADC4836H | \$ 884.75 |
| OADC4836HBA | \$ 1,061.70 |
| OADC4836HI | \$ 1,089.13 |
| OADC4836HIBA | \$ 1,306.95 |
| OADC4836I | \$ 1,035.34 |
| OADC4836IBA | \$ 1,242.41 |
| OADC4860 | \$ 1,285.44 |

| | |
|----------------|-------------|
| OADC4860BA | \$ 1,542.53 |
| OADC4860H | \$ 1,203.42 |
| OADC4860HBA | \$ 1,444.10 |
| OADC4860HI | \$ 1,411.84 |
| OADC4860HIBA | \$ 1,694.19 |
| OADC4860I | \$ 1,340.56 |
| OADC4860IBA | \$ 1,608.69 |
| OADC4872-3 | \$ 1,277.38 |
| OADC4872-3BA | \$ 1,610.01 |
| OADC4872-3H | \$ 1,573.19 |
| OADC4872-3HBA | \$ 1,887.82 |
| OADC4872-3HI | \$ 1,891.85 |
| OADC4872-3HIBA | \$ 2,270.22 |
| OADC4872-3I | \$ 1,801.77 |
| OADC4872-3IBA | \$ 2,162.11 |
| OADC4872BA | \$ 1,686.13 |
| OADC4872H | \$ 1,458.89 |
| OADC4872HBA | \$ 1,750.67 |
| OADC4872HI | \$ 1,700.92 |
| OADC4872HIBA | \$ 2,041.11 |
| OADC4872I | \$ 1,620.24 |
| OADC4872IBA | \$ 1,944.29 |
| OADC4896-3 | \$ 1,589.31 |
| OADC4896-3BA | \$ 1,907.18 |
| OADC4896-3H | \$ 1,909.33 |
| OADC4896-3HBA | \$ 2,291.19 |
| OADC4896-3HI | \$ 2,252.21 |
| OADC4896-3HIBA | \$ 2,702.65 |
| OADC4896-3I | \$ 2,144.64 |
| OADC4896-3IBA | \$ 2,573.57 |
| OADCO2418R | \$ 361.13 |
| OADCO3624R | \$ 425.28 |
| OADCO3630R | \$ 463.27 |
| OADCO3636R | \$ 556.12 |
| OADCO3648R | \$ 726.55 |
| OADCO3660R | \$ 851.73 |
| OADCO4836R | \$ 677.65 |
| OADCW2418R | \$ 361.13 |
| OADCW3624R | \$ 425.28 |
| OADCW3630R | \$ 463.27 |
| OADCW3636R | \$ 556.12 |
| OADCW3648R | \$ 726.55 |
| OADCW3660R | \$ 851.73 |
| OADCW4836R | \$ 677.64 |
| OADCWW2418R | \$ 361.13 |
| OADCWW3624R | \$ 425.28 |
| OADCWW3630R | \$ 463.27 |

| | |
|-------------|-----------|
| OADCWW3636R | \$ 556.12 |
| OADCWW3648R | \$ 726.55 |
| OADCWW3660R | \$ 851.73 |
| OADCWW4836R | \$ 677.65 |
| OB1824 | \$ 26.63 |
| OB2436 | \$ 40.72 |
| OB3648 | \$ 68.87 |
| OB3660 | \$ 129.96 |
| OB48120 | \$ 294.58 |
| OB48144 | \$ 355.23 |
| OB4848 | \$ 138.63 |
| OB4860 | \$ 170.67 |
| OB4872 | \$ 232.53 |
| OB4896 | \$ 247.75 |
| OBC2418R | \$ 204.50 |
| OBC2418RH | \$ 245.44 |
| OBC2418S | \$ 257.23 |
| OBC2418S | \$ 257.23 |
| OBC2424S | \$ 333.23 |
| OBC2424S | \$ 333.23 |
| OBC3624R | \$ 237.94 |
| OBC3624RC | \$ 273.63 |
| OBC3624RH | \$ 308.67 |
| OBC3624S | \$ 403.38 |
| OBC3624S | \$ 403.38 |
| OBC3630R | \$ 286.80 |
| OBC3630RH | \$ 469.44 |
| OBC3636R | \$ 344.18 |
| OBC3636RH | \$ 563.34 |
| OBC3648R | \$ 424.42 |
| OBC3648RC | \$ 485.52 |
| OBC3648RH | \$ 578.76 |
| OBC3648S | \$ 549.54 |
| OBC3648S | \$ 549.54 |
| OBC3660R | \$ 535.53 |
| OBC3660RC | \$ 614.78 |
| OBC3660RH | \$ 662.37 |
| OBC3672-3R | \$ 688.51 |
| OBC3672-3RH | \$ 848.85 |
| OBC3672R | \$ 619.92 |
| OBC3672RC | \$ 791.79 |
| OBC3672RH | \$ 763.97 |
| OBC4836R | \$ 398.71 |
| OBC4836RH | \$ 537.61 |
| OBC4860R | \$ 694.52 |
| OBC4860RH | \$ 720.23 |
| OBC4872-3R | \$ 790.98 |

| | |
|-------------|-------------|
| OBC4872-3RH | \$ 964.60 |
| OBC4872R | \$ 737.22 |
| OBC4872RC | \$ 909.63 |
| OBC4872RH | \$ 861.72 |
| OBC4896-3R | \$ 893.87 |
| OBC4896-3RH | \$ 1,176.82 |
| OBC4896RC | \$ 1,027.95 |
| OC-1 | \$ 913.16 |
| OC1218NT | \$ 24.58 |
| OC1824G | \$ 33.24 |
| OC1824NT | \$ 32.27 |
| OC-2 | \$ 1,067.49 |
| OC2436G | \$ 46.90 |
| OC2436NT | \$ 45.53 |
| OC3648G | \$ 79.71 |
| OC3648NT | \$ 77.38 |
| OC3660G | \$ 156.38 |
| OC3660NT | \$ 151.83 |
| OC48120G | \$ 350.93 |
| OC48144G | \$ 424.26 |
| OC4860G | \$ 174.63 |
| OC4872G | \$ 213.78 |
| OC4896G | \$ 285.54 |
| ODC2418 | \$ 265.40 |
| ODC2418H | \$ 364.46 |
| ODC3624 | \$ 314.15 |
| ODC3624H | \$ 463.50 |
| ODC3630 | \$ 347.25 |
| ODC3630H | \$ 527.32 |
| ODC3636 | \$ 416.71 |
| ODC3636H | \$ 632.69 |
| ODC3648 | \$ 527.32 |
| ODC3648H | \$ 785.84 |
| ODC3660 | \$ 639.21 |
| ODC3660H | \$ 944.68 |
| ODC3672 | \$ 863.01 |
| ODC3672-3 | \$ 962.04 |
| ODC3672-3H | \$ 1,331.16 |
| ODC3672H | \$ 1,221.19 |
| ODC4836 | \$ 511.88 |
| ODC4836H | \$ 715.22 |
| ODC4860 | \$ 790.98 |
| ODC4860H | \$ 1,044.34 |
| ODC4872 | \$ 1,142.09 |
| ODC4872-3 | \$ 1,048.21 |
| ODC4872-3H | \$ 1,424.63 |
| ODC4872H | \$ 1,552.85 |

| | |
|---------------|-------------|
| ODC4896-3 | \$ 1,124.93 |
| ODC4896-3H | \$ 1,565.23 |
| ODCC2412R | \$ 256.79 |
| ODCC2412RBA | \$ 308.15 |
| ODCC2418R | \$ 273.46 |
| ODCC2418RBA | \$ 328.15 |
| ODCC2418RH | \$ 349.59 |
| ODCC2418RHBA | \$ 419.52 |
| ODCC2418RHI | \$ 485.40 |
| ODCC2418RHIBA | \$ 582.48 |
| ODCC2418RI | \$ 365.73 |
| ODCC2418RIBA | \$ 438.88 |
| ODCC3612R | \$ 304.87 |
| ODCC3612RBA | \$ 365.84 |
| ODCC3624R | \$ 348.40 |
| ODCC3624RBA | \$ 418.07 |
| ODCC3624RH | \$ 469.26 |
| ODCC3624RHBA | \$ 563.12 |
| ODCC3624RHI | \$ 638.69 |
| ODCC3624RHIBA | \$ 766.43 |
| ODCC3624RI | \$ 563.67 |
| ODCC3624RIBA | \$ 676.41 |
| ODCC3630R | \$ 383.21 |
| ODCC3630RBA | \$ 459.85 |
| ODCC3630RH | \$ 527.63 |
| ODCC3630RHBA | \$ 640.57 |
| ODCC3630RHI | \$ 735.49 |
| ODCC3630RHIBA | \$ 882.59 |
| ODCC3630RI | \$ 685.76 |
| ODCC3630RIBA | \$ 822.90 |
| ODCC3636R | \$ 459.85 |
| ODCC3636RBA | \$ 551.83 |
| ODCC3636RH | \$ 640.57 |
| ODCC3636RHBA | \$ 768.68 |
| ODCC3636RHI | \$ 882.59 |
| ODCC3636RHIBA | \$ 1,059.12 |
| ODCC3636RI | \$ 822.90 |
| ODCC3636RIBA | \$ 987.48 |
| ODCC3648R | \$ 602.79 |
| ODCC3648RBA | \$ 723.34 |
| ODCC3648RH | \$ 806.76 |
| ODCC3648RHBA | \$ 968.11 |
| ODCC3648RHI | \$ 1,062.24 |
| ODCC3648RHIBA | \$ 1,274.68 |
| ODCC3648RI | \$ 997.15 |
| ODCC3648RIBA | \$ 1,196.59 |
| ODCC3660R | \$ 722.69 |

| | |
|-----------------|-------------|
| ODCC3660RBA | \$ 867.22 |
| ODCC3660RH | \$ 907.61 |
| ODCC3660RHBA | \$ 1,089.13 |
| ODCC3660RHI | \$ 1,183.24 |
| ODCC3660RHIBA | \$ 1,419.90 |
| ODCC3660RI | \$ 1,199.35 |
| ODCC3660RIBA | \$ 1,439.23 |
| ODCC3672-3R | \$ 923.63 |
| ODCC3672-3RBA | \$ 1,108.35 |
| ODCC3672-3RH | \$ 1,125.43 |
| ODCC3672-3RHBA | \$ 1,350.52 |
| ODCC3672-3RHI | \$ 1,550.32 |
| ODCC3672-3RHIBA | \$ 1,860.39 |
| ODCC3672-3RI | \$ 1,528.97 |
| ODCC3672-3RIBA | \$ 1,834.78 |
| ODCC3672R | \$ 837.88 |
| ODCC3672RBA | \$ 1,005.48 |
| ODCC3672RH | \$ 1,075.68 |
| ODCC3672RHBA | \$ 1,290.82 |
| ODCC3672RHI | \$ 1,384.95 |
| ODCC3672RHIBA | \$ 1,661.93 |
| ODCC3672RI | \$ 1,382.52 |
| ODCC3672RIBA | \$ 1,659.02 |
| ODCC4836R | \$ 571.45 |
| ODCC4836RBA | \$ 685.76 |
| ODCC4836RH | \$ 748.94 |
| ODCC4836RHBA | \$ 898.74 |
| ODCC4836RHI | \$ 1,005.75 |
| ODCC4836RHIBA | \$ 1,206.91 |
| ODCC4836RI | \$ 907.61 |
| ODCC4836RIBA | \$ 1,089.13 |
| ODCC4860R | \$ 991.68 |
| ODCC4860RBA | \$ 1,190.00 |
| ODCC4860RH | \$ 988.28 |
| ODCC4860RHBA | \$ 1,185.93 |
| ODCC4860RHI | \$ 1,479.06 |
| ODCC4860RHIBA | \$ 1,774.88 |
| ODCC4860RI | \$ 1,549.01 |
| ODCC4860RIBA | \$ 1,858.81 |
| ODCC4872-3R | \$ 1,111.59 |
| ODCC4872-3RBA | \$ 1,333.90 |
| ODCC4872-3RH | \$ 1,246.44 |
| ODCC4872-3RHBA | \$ 1,495.73 |
| ODCC4872-3RHI | \$ 1,747.98 |
| ODCC4872-3RHIBA | \$ 2,097.57 |
| ODCC4872-3RI | \$ 1,912.60 |
| ODCC4872-3RIBA | \$ 2,295.12 |

| | |
|-----------------|-------------|
| ODCC4872R | \$ 1,095.38 |
| ODCC4872RBA | \$ 1,314.47 |
| ODCC4872RH | \$ 1,196.71 |
| ODCC4872RHBA | \$ 1,436.03 |
| ODCC4872RHI | \$ 1,573.19 |
| ODCC4872RHIBA | \$ 1,887.82 |
| ODCC4872RI | \$ 1,752.71 |
| ODCC4872RIBA | \$ 2,103.26 |
| ODCC4896-3R | \$ 1,451.86 |
| ODCC4896-3RBA | \$ 1,742.23 |
| ODCC4896-3RH | \$ 1,566.45 |
| ODCC4896-3RHBA | \$ 1,879.75 |
| ODCC4896-3RHI | \$ 2,050.52 |
| ODCC4896-3RHIBA | \$ 2,460.63 |
| ODCC4896-3RI | \$ 2,202.07 |
| ODCC4896-3RIBA | \$ 2,642.47 |
| ODCCO2418R | \$ 292.60 |
| ODCCO3624R | \$ 372.79 |
| ODCCO3630R | \$ 410.03 |
| ODCCO3636R | \$ 492.05 |
| ODCCO3648R | \$ 644.97 |
| ODCCO3660R | \$ 773.26 |
| ODCCO4836R | \$ 611.46 |
| ODCCW2418R | \$ 292.60 |
| ODCCW3624R | \$ 372.79 |
| ODCCW3630R | \$ 410.03 |
| ODCCW3636R | \$ 492.05 |
| ODCCW3648R | \$ 644.97 |
| ODCCW3660R | \$ 773.26 |
| ODCCW4836R | \$ 611.46 |
| ODCCWW2418R | \$ 255.52 |
| ODCCWW3624R | \$ 372.79 |
| ODCCWW3630R | \$ 410.03 |
| ODCCWW3636R | \$ 492.05 |
| ODCCWW3648R | \$ 644.97 |
| ODCCWW3660R | \$ 773.26 |
| ODCCWW4836R | \$ 611.46 |
| OF1218014 | \$ 22.68 |
| OF1824014 | \$ 39.47 |
| OF2436014 | \$ 58.61 |
| OF3648014 | \$ 117.22 |
| OF48120014 | \$ 391.15 |
| OF48144014 | \$ 461.23 |
| OF4848014 | \$ 155.44 |
| OF4872014 | \$ 229.34 |
| OF4896014 | \$ 307.07 |
| OP-36 | \$ 417.29 |

| | |
|-------------|-------------|
| OP-40 | \$ 556.39 |
| OP-48 | \$ 642.11 |
| OPE02L | \$ 176.45 |
| OPE02S | \$ 93.95 |
| OPLD1818-2 | \$ 272.95 |
| OPLD1818L-2 | \$ 293.55 |
| OPLD3416-2 | \$ 324.45 |
| OPLD3416L-2 | \$ 341.96 |
| ORC1824TAN | \$ 57.59 |
| ORC2436TAN | \$ 84.45 |
| ORC3648TAN | \$ 130.01 |
| ORC48120TAN | \$ 342.78 |
| ORC48144TAN | \$ 418.14 |
| ORC4848TAN | \$ 173.80 |
| ORC4872TAN | \$ 241.94 |
| ORC4896TAN | \$ 291.09 |
| OS1824G | \$ 77.29 |
| OS2436G | \$ 134.09 |
| OS3648G | \$ 242.73 |
| OS3660G | \$ 361.92 |
| OS48120G | \$ 770.68 |
| OS48144G | \$ 899.32 |
| OS48192G | \$ 1,319.02 |
| OS4860G | \$ 402.94 |
| OS4872G | \$ 479.23 |
| OS4896G | \$ 610.47 |
| OT118 | \$ 30.64 |
| OT1711 | \$ 42.16 |
| OT2217 | \$ 53.24 |
| OT2822 | \$ 74.58 |
| OT3624 | \$ 77.74 |
| OT4428 | \$ 98.82 |
| OV1218700 | \$ 18.91 |
| OV1824700 | \$ 32.89 |
| OV2436700 | \$ 58.75 |
| OV3648700 | \$ 90.72 |
| OV3660700 | \$ 175.17 |
| OV48120700 | \$ 362.72 |
| OV48144700 | \$ 438.03 |
| OV4848700 | \$ 163.47 |
| OV4860700 | \$ 175.17 |
| OV4872700 | \$ 193.95 |
| OV4896700 | \$ 253.35 |
| OVB48120 | \$ 729.49 |
| OVB48144 | \$ 869.41 |
| OVB48192 | \$ 1,225.34 |
| OVB4872 | \$ 458.98 |

| | |
|--------------|-------------|
| OVB4872V2 | \$ 458.98 |
| OVB4896 | \$ 582.04 |
| OVC-1 | \$ 1,430.18 |
| OVC-2 | \$ 1,841.74 |
| OW2436166 | \$ 120.31 |
| OW3648166 | \$ 218.95 |
| OW48120166 | \$ 666.74 |
| OW48144166 | \$ 778.07 |
| OW48192166 | \$ 1,100.94 |
| OW4848166 | \$ 290.70 |
| OW4872166 | \$ 416.87 |
| OW4896166 | \$ 548.00 |
| OWFC2418 | \$ 287.93 |
| OWFC2418G | \$ 306.93 |
| OWFC2418LB | \$ 306.93 |
| OWFC3624 | \$ 372.68 |
| OWFC3624G | \$ 401.91 |
| OWFC3624LB | \$ 401.91 |
| OWFC3648 | \$ 635.75 |
| OWFC3648G | \$ 679.61 |
| OWFC3648LB | \$ 679.61 |
| P-15B | \$ 470.40 |
| P-15BK | \$ 403.20 |
| P-15C | \$ 416.64 |
| P-17B | \$ 520.47 |
| P-17BK | \$ 461.17 |
| P-17C | \$ 480.94 |
| P31-B | \$ 738.21 |
| P31-C | \$ 645.64 |
| P-5B | \$ 434.82 |
| P-5BK | \$ 408.47 |
| P-5C | \$ 421.64 |
| P-7B | \$ 508.61 |
| P-7BK | \$ 483.57 |
| P-7C | \$ 492.80 |
| PC1204848 | \$ 549.06 |
| PFS1114 | \$ 148.95 |
| PHSIB | \$ 137.92 |
| PHSIC | \$ 148.53 |
| PIZ01L | \$ 176.45 |
| PIZ01S | \$ 93.96 |
| PL1204872 | \$ 690.43 |
| PLD3045-2-2 | \$ 700.40 |
| PLD3045-2L-2 | \$ 746.75 |
| PLD3045T-2 | \$ 633.45 |
| PLD3045TL-2 | \$ 654.05 |
| PLD3645-2-2 | \$ 854.90 |

| | |
|--------------|-------------|
| PLD3645-2L-2 | \$ 875.50 |
| PLD3645T-2 | \$ 764.26 |
| PLD3645TL-2 | \$ 795.16 |
| PLD4052-2-2 | \$ 1,041.33 |
| PLD4052-2L-2 | \$ 1,091.80 |
| PLD4052T-2 | \$ 957.90 |
| PLD4052TL-2 | \$ 988.80 |
| PLD4226-2 | \$ 604.61 |
| PLD4226L-2 | \$ 638.60 |
| PLD4832-2 | \$ 690.10 |
| PLD4832L-2 | \$ 757.05 |
| PLD5438-2 | \$ 793.10 |
| PLD5438L-2 | \$ 849.75 |
| PLDS3045-2 | \$ 659.20 |
| PLDS3045L-2 | \$ 710.70 |
| PLDS3645-2 | \$ 839.45 |
| PLDS3645L-2 | \$ 869.32 |
| PLDS4052-2 | \$ 1,037.21 |
| PLDS4052L-2 | \$ 1,076.35 |
| POD-1 | \$ 1,352.01 |
| POD-2 | \$ 1,437.94 |
| PS48120 | \$ 360.71 |
| PS48144 | \$ 432.85 |
| PS48192 | \$ 577.13 |
| PS4872 | \$ 216.42 |
| PS4896 | \$ 288.56 |
| PSA48120 | \$ 542.12 |
| PSA48144 | \$ 651.57 |
| PSA4872 | \$ 325.70 |
| PSA4896 | \$ 433.91 |
| R1236 | \$ 29.63 |
| R1248 | \$ 40.87 |
| R1824 | \$ 28.17 |
| R2436 | \$ 43.88 |
| R3648 | \$ 79.81 |
| RAB3624BL | \$ 334.80 |
| RAB3624BU | \$ 334.80 |
| RAB3624GG | \$ 334.80 |
| RAB3648BL | \$ 506.92 |
| RAB3648BU | \$ 506.92 |
| RAB3648GG | \$ 506.92 |
| RAB3660BL | \$ 626.78 |
| RAB3660BU | \$ 626.78 |
| RAB3660GG | \$ 626.78 |
| RAB3672BL | \$ 768.78 |
| RAB3672BU | \$ 768.78 |
| RAB3672GG | \$ 768.78 |

| | |
|------------|-----------|
| RAD3624BB | \$ 379.18 |
| RAD3624BU | \$ 379.18 |
| RAD3624GB | \$ 379.18 |
| RAD3648BB | \$ 602.58 |
| RAD3648BU | \$ 602.58 |
| RAD3648GB | \$ 602.58 |
| RAD3660BB | \$ 769.11 |
| RAD3660BU | \$ 769.11 |
| RAD3660GB | \$ 769.11 |
| RAD3672BB | \$ 938.54 |
| RAD3672BU | \$ 938.54 |
| RAD3672GB | \$ 938.54 |
| RAF-1 | \$ 243.08 |
| RAF-2 | \$ 284.28 |
| RAF-3 | \$ 243.08 |
| RAF-4 | \$ 284.28 |
| RAF-5 | \$ 229.69 |
| RAF-6 | \$ 175.10 |
| RB1114 | \$ 21.77 |
| RB1824 | \$ 50.72 |
| RB-2 | \$ 157.54 |
| RB2436 | \$ 68.97 |
| RB3648 | \$ 114.78 |
| RBB3648 | \$ 378.94 |
| RBB4260 | \$ 464.74 |
| RBB4872 | \$ 514.78 |
| RBC3648B | \$ 370.65 |
| RBC4260B | \$ 480.46 |
| RBC4872B | \$ 509.05 |
| RC3648B | \$ 298.81 |
| RC4260B | \$ 395.33 |
| RC4872B | \$ 449.55 |
| RDF1824014 | \$ 34.40 |
| RDF2436014 | \$ 57.34 |
| RDF3648014 | \$ 91.74 |
| RDF4848014 | \$ 127.41 |
| RDF4872014 | \$ 163.09 |
| RDS2436 | \$ 244.94 |
| RDS3648 | \$ 398.30 |
| RDS3660 | \$ 450.16 |
| RDS48120 | \$ 789.99 |
| RDS48144 | \$ 874.95 |
| RDS4860 | \$ 502.02 |
| RDS4872 | \$ 552.77 |
| RDS4896 | \$ 686.27 |
| RF1248BK | \$ 62.51 |
| RF1824BK | \$ 51.16 |

| | |
|-----------|-----------|
| RF2436BK | \$ 73.81 |
| RF3648BK | \$ 110.37 |
| RF4860BK | \$ 176.07 |
| RF4872BK | \$ 193.95 |
| RHD24B | \$ 227.23 |
| RHD24B | \$ 227.23 |
| RHD24G | \$ 227.23 |
| RHD24G | \$ 227.23 |
| RHD24M | \$ 227.23 |
| RHD24M | \$ 227.23 |
| RHD48B | \$ 343.85 |
| RHD48B | \$ 343.85 |
| RHD48G | \$ 343.85 |
| RHD48G | \$ 343.85 |
| RHD48M | \$ 343.85 |
| RHD48M | \$ 343.85 |
| RHD60B | \$ 457.16 |
| RHD60B | \$ 457.16 |
| RHD60G | \$ 457.16 |
| RHD60G | \$ 457.16 |
| RHD60M | \$ 457.16 |
| RHD60M | \$ 457.16 |
| RHD72B | \$ 572.79 |
| RHD72B | \$ 572.80 |
| RHD72G | \$ 572.79 |
| RHD72G | \$ 572.80 |
| RHD72M | \$ 572.79 |
| RHD72M | \$ 572.80 |
| RHI2418F | \$ 56.32 |
| RHI2418F | \$ 56.32 |
| RHI2418RH | \$ 56.32 |
| RHI2418V | \$ 56.32 |
| RHI2418V | \$ 56.32 |
| RHI3624F | \$ 87.61 |
| RHI3624F | \$ 87.61 |
| RHI3624RH | \$ 87.61 |
| RHI3624V | \$ 87.61 |
| RHI3624V | \$ 87.61 |
| RHI3630F | \$ 155.78 |
| RHI3630F | \$ 155.78 |
| RHI3630RH | \$ 155.78 |
| RHI3630V | \$ 155.78 |
| RHI3630V | \$ 155.78 |
| RHI3636F | \$ 128.28 |
| RHI3636F | \$ 128.28 |
| RHI3636RH | \$ 186.46 |
| RHI3636V | \$ 128.28 |

| | |
|-----------|-----------|
| RHI3636V | \$ 128.28 |
| RHI4824F | \$ 166.16 |
| RHI4824F | \$ 166.16 |
| RHI4824RH | \$ 166.16 |
| RHI4824V | \$ 166.16 |
| RHI4824V | \$ 166.16 |
| RHI4830F | \$ 207.71 |
| RHI4830F | \$ 207.71 |
| RHI4830RH | \$ 207.71 |
| RHI4830V | \$ 207.71 |
| RHI4830V | \$ 207.71 |
| RHI4832F | \$ 205.10 |
| RHI4832F | \$ 205.10 |
| RHI4832RH | \$ 205.10 |
| RHI4832V | \$ 205.10 |
| RHI4832V | \$ 205.10 |
| RHI4836F | \$ 218.08 |
| RHI4836F | \$ 218.08 |
| RHI4836RH | \$ 218.08 |
| RHI4836V | \$ 218.08 |
| RHI4836V | \$ 218.08 |
| RMB1824 | \$ 48.93 |
| RMB2436 | \$ 80.34 |
| RMB3648 | \$ 167.89 |
| ROC-1 | \$ 247.20 |
| ROC-2 | \$ 211.15 |
| ROC-3 | \$ 233.81 |
| ROC-4 | \$ 275.01 |
| ROC-5 | \$ 233.81 |
| ROC-6 | \$ 275.01 |
| ROC-7 | \$ 484.10 |
| ROC-8 | \$ 535.60 |
| ROCLTR-1 | \$ 62.83 |
| ROCLTR-1 | \$ 62.83 |
| ROCLTR-2 | \$ 62.83 |
| ROCLTR-2 | \$ 62.83 |
| RR2418F | \$ 56.32 |
| RR2418F | \$ 56.32 |
| RR2418V | \$ 64.85 |
| RR3624F | \$ 87.61 |
| RR3624F | \$ 87.61 |
| RR3624V | \$ 101.06 |
| RR3630F | \$ 155.78 |
| RR3630F | \$ 155.78 |
| RR3630V | \$ 179.14 |
| RR3636F | \$ 128.28 |
| RR3636F | \$ 128.28 |

| | |
|-----------|-----------|
| RR3636V | \$ 147.98 |
| RR4824F | \$ 166.16 |
| RR4824F | \$ 166.16 |
| RR4824V | \$ 192.12 |
| RR4830F | \$ 207.70 |
| RR4830F | \$ 207.71 |
| RR4830V | \$ 240.16 |
| RR4832F | \$ 205.10 |
| RR4832F | \$ 205.10 |
| RR4832V | \$ 236.27 |
| RR4836F | \$ 218.08 |
| RR4836F | \$ 218.08 |
| RR4836V | \$ 251.85 |
| RS3648S | \$ 568.55 |
| RS4260S | \$ 695.47 |
| RS4872S | \$ 786.71 |
| RSB3648BL | \$ 539.18 |
| RSB3648BU | \$ 539.18 |
| RSB3648GG | \$ 539.18 |
| RSB3660BL | \$ 658.12 |
| RSB3660BU | \$ 658.12 |
| RSB3660GG | \$ 658.12 |
| RSB3672BL | \$ 852.82 |
| RSB3672BU | \$ 852.82 |
| RSB3672GG | \$ 852.82 |
| RSD3648BB | \$ 622.48 |
| RSD3648BU | \$ 622.48 |
| RSD3648GB | \$ 622.48 |
| RSD3660BB | \$ 763.72 |
| RSD3660BU | \$ 763.72 |
| RSD3660GB | \$ 763.72 |
| RSD3672BB | \$ 950.63 |
| RSD3672BU | \$ 950.63 |
| RSD3672GB | \$ 950.63 |
| RV1824700 | \$ 32.62 |
| RV2436700 | \$ 52.56 |
| RV3648700 | \$ 86.64 |
| RV4848700 | \$ 114.67 |
| RV4872700 | \$ 149.07 |
| RW1248 | \$ 66.95 |
| RW1824 | \$ 45.67 |
| RW2436 | \$ 62.77 |
| RW3648 | \$ 95.91 |
| RW4872 | \$ 228.03 |
| SAL05L | \$ 176.45 |
| SAL05S | \$ 93.96 |
| SB15W | \$ 79.07 |

| | |
|-----------|-------------|
| SB-1C | \$ 525.17 |
| SB40F | \$ 306.83 |
| SBC3648 | \$ 642.52 |
| SBC3648B | \$ 771.03 |
| SBC3648BK | \$ 771.03 |
| SBC3648G | \$ 771.03 |
| SBC3648IV | \$ 771.03 |
| SBC3648R | \$ 771.03 |
| SBC3648W | \$ 771.03 |
| SBC3660 | \$ 782.89 |
| SBC3660B | \$ 939.48 |
| SBC3660BK | \$ 939.48 |
| SBC3660G | \$ 939.48 |
| SBC3660IV | \$ 939.48 |
| SBC3660R | \$ 939.48 |
| SBC3660W | \$ 939.48 |
| SBC4872 | \$ 1,157.85 |
| SBC4872B | \$ 1,389.41 |
| SBC4872BK | \$ 1,389.41 |
| SBC4872G | \$ 1,389.41 |
| SBC4872IV | \$ 1,389.41 |
| SBC4872R | \$ 1,389.41 |
| SBC4872W | \$ 1,389.41 |
| SC15W | \$ 83.79 |
| SC40F | \$ 328.08 |
| SDC3648 | \$ 785.59 |
| SDC3648R | \$ 942.72 |
| SDC3660 | \$ 916.20 |
| SDC3660R | \$ 1,099.45 |
| SDC4872 | \$ 1,376.53 |
| SDC4872R | \$ 1,651.83 |
| SF1824014 | \$ 34.40 |
| SF2436014 | \$ 57.34 |
| SF3648014 | \$ 91.74 |
| SF4848014 | \$ 127.41 |
| SF4872014 | \$ 163.09 |
| SMD1218 | \$ 161.50 |
| SMD1418 | \$ 184.58 |
| SN1185 | \$ 26.95 |
| SN1411 | \$ 35.22 |
| SN2228 | \$ 68.28 |
| SPP | \$ 185.40 |
| SS15W | \$ 70.81 |
| SS40F | \$ 283.24 |
| ST-2 | \$ 170.15 |
| SV1824700 | \$ 32.62 |
| SV1824703 | \$ 32.62 |

| | | |
|-----------|----|--------|
| SV2436700 | \$ | 52.56 |
| SV3648700 | \$ | 86.64 |
| SV4848700 | \$ | 114.67 |
| SV4872700 | \$ | 149.07 |
| T1 | \$ | 40.33 |
| TA-1 | \$ | 35.01 |
| TA-11 | \$ | 35.59 |
| TA-1P | \$ | 43.18 |
| TA-5 | \$ | 36.76 |
| TAK12M | \$ | 116.70 |
| TE1BK | \$ | 293.86 |
| TI-1B | \$ | 166.14 |
| TI-1BK | \$ | 160.41 |
| TI-1CH | \$ | 154.68 |
| TPS-50 | \$ | 201.21 |
| TPS-70 | \$ | 306.37 |
| TPS-84 | \$ | 382.95 |
| Tr-1 | \$ | 22.61 |
| Tr-10 | \$ | 44.23 |
| Tr-105 | \$ | 41.61 |
| Tr-11 | \$ | 41.61 |
| Tr-12 | \$ | 44.23 |
| Tr-125 | \$ | 41.61 |
| Tr-126 | \$ | 41.61 |
| Tr-127 | \$ | 44.23 |
| Tr-128 | \$ | 41.61 |
| Tr-2 | \$ | 25.22 |
| Tr-25 | \$ | 22.61 |
| Tr-3 | \$ | 22.61 |
| Tr-4 | \$ | 25.22 |
| Tr-45 | \$ | 22.61 |
| Tr-46 | \$ | 22.61 |
| Tr-47 | \$ | 25.22 |
| Tr-48 | \$ | 22.61 |
| Tr-5 | \$ | 27.20 |
| Tr-6 | \$ | 29.79 |
| Tr-65 | \$ | 27.20 |
| Tr-7 | \$ | 27.20 |
| Tr-8 | \$ | 29.79 |
| Tr-85 | \$ | 27.20 |
| Tr-86 | \$ | 27.20 |
| Tr-87 | \$ | 29.79 |
| Tr-88 | \$ | 27.20 |
| Tr-9 | \$ | 41.61 |
| TS-1 | \$ | 74.13 |
| TS-2 | \$ | 74.13 |
| TS-3 | \$ | 74.13 |

| | |
|------------|-----------|
| TY-2B | \$ 154.68 |
| TY-2BK | \$ 148.95 |
| TY-2CH | \$ 143.22 |
| USA1204872 | \$ 690.43 |
| VHF-1 | \$ 81.95 |
| VSF118B | \$ 84.90 |
| VSF118BK | \$ 71.84 |
| VSF118C | \$ 78.15 |
| VSF118S | \$ 84.90 |
| VSF1411B | \$ 102.09 |
| VSF1411BK | \$ 88.22 |
| VSF1411C | \$ 94.87 |
| VSF1411S | \$ 102.09 |
| WAC1824 | \$ 30.28 |
| WAC2436 | \$ 49.52 |
| WAC3648 | \$ 79.42 |
| WAC3660 | \$ 155.15 |
| WAC4860 | \$ 170.49 |
| WAC4872 | \$ 205.98 |
| WAC4896 | \$ 258.14 |
| WACB3648 | \$ 580.57 |
| WACB4260 | \$ 635.86 |
| WACB4872 | \$ 718.79 |
| WARC3648 | \$ 573.66 |
| WARC4260 | \$ 649.68 |
| WARC4872 | \$ 739.54 |
| WARS3648 | \$ 677.33 |
| WARS4260 | \$ 794.83 |
| WARS4872 | \$ 898.50 |
| WBC2418R | \$ 223.79 |
| WBC2418RH | \$ 273.95 |
| WBC2418S | \$ 257.23 |
| WBC2418S | \$ 257.23 |
| WBC2424S | \$ 333.23 |
| WBC2424S | \$ 333.23 |
| WBC3624R | \$ 261.09 |
| WBC3624RC | \$ 304.82 |
| WBC3624RH | \$ 335.69 |
| WBC3624S | \$ 403.38 |
| WBC3624S | \$ 403.38 |
| WBC3630R | \$ 315.11 |
| WBC3630RH | \$ 501.59 |
| WBC3636R | \$ 378.13 |
| WBC3636RH | \$ 601.92 |
| WBC3648R | \$ 458.38 |
| WBC3648RC | \$ 533.76 |
| WBC3648RH | \$ 625.06 |

| | |
|-------------|-------------|
| WBC3648S | \$ 549.54 |
| WBC3648S | \$ 549.54 |
| WBC3660R | \$ 578.25 |
| WBC3660RC | \$ 675.23 |
| WBC3660RH | \$ 713.81 |
| WBC3672-3R | \$ 733.27 |
| WBC3672-3RH | \$ 904.15 |
| WBC3672R | \$ 669.51 |
| WBC3672RC | \$ 870.72 |
| WBC3672RH | \$ 816.71 |
| WBC4836R | \$ 430.60 |
| WBC4836RH | \$ 580.05 |
| WBC4860R | \$ 739.65 |
| WBC4860RH | \$ 767.05 |
| WBC4872-3R | \$ 842.40 |
| WBC4872-3RH | \$ 1,023.77 |
| WBC4872R | \$ 785.14 |
| WBC4872RC | \$ 999.97 |
| WBC4872RH | \$ 917.66 |
| WBC4896-3R | \$ 947.51 |
| WBC4896-3RH | \$ 1,246.27 |
| WBC4896RC | \$ 1,130.52 |
| WC-1 | \$ 913.16 |
| WC-2 | \$ 1,067.49 |
| WCO2436 | \$ 79.74 |
| WCO3648 | \$ 118.75 |
| WCO4872 | \$ 208.30 |
| WCO4896 | \$ 277.63 |
| WCS12 | \$ 12.69 |
| WCS12 | \$ 12.32 |
| WCS12 | \$ 12.32 |
| WCS-144 | \$ 143.22 |
| WDC2418 | \$ 290.81 |
| WDC2418H | \$ 396.73 |
| WDC3624 | \$ 343.35 |
| WDC3624H | \$ 501.59 |
| WDC3630 | \$ 378.17 |
| WDC3630H | \$ 571.05 |
| WDC3636 | \$ 453.81 |
| WDC3636H | \$ 685.26 |
| WDC3648 | \$ 569.51 |
| WDC3648H | \$ 861.45 |
| WDC3660 | \$ 687.13 |
| WDC3660H | \$ 1,014.84 |
| WDC3672 | \$ 916.50 |
| WDC3672-3 | \$ 1,029.38 |
| WDC3672-3H | \$ 1,424.33 |

| | |
|------------|-------------|
| WDC3672H | \$ 1,299.90 |
| WDC4836 | \$ 552.86 |
| WDC4836H | \$ 769.11 |
| WDC4860 | \$ 844.73 |
| WDC4860H | \$ 1,117.45 |
| WDC4872 | \$ 1,212.91 |
| WDC4872-3 | \$ 1,113.19 |
| WDC4872-3H | \$ 1,509.15 |
| WDC4872H | \$ 1,653.27 |
| WDC4896-3 | \$ 1,194.44 |
| WDC4896-3H | \$ 1,659.14 |
| WDCO2436 | \$ 95.28 |
| WDCO3648 | \$ 142.38 |
| WDCO4872 | \$ 277.63 |
| WDCO4896 | \$ 370.02 |
| WDS1824 | \$ 68.81 |
| WDS1824M | \$ 80.12 |
| WDS2436 | \$ 120.51 |
| WDS2436M | \$ 135.11 |
| WDS3648 | \$ 243.08 |
| WDS3648M | \$ 260.96 |
| WDS3660 | \$ 255.44 |
| WDS3660M | \$ 276.61 |
| WDS48120 | \$ 572.68 |
| WDS48120M | \$ 610.28 |
| WDS48144 | \$ 651.99 |
| WDS48144M | \$ 696.16 |
| WDS48192 | \$ 865.20 |
| WDS48192M | \$ 922.51 |
| WDS4860 | \$ 319.30 |
| WDS4860M | \$ 340.47 |
| WDS4872 | \$ 366.68 |
| WDS4872M | \$ 391.13 |
| WDS4896 | \$ 481.01 |
| WDS4896M | \$ 512.03 |
| WE60 | \$ 56.15 |
| WFC2418 | \$ 223.63 |
| WFC2418G | \$ 238.38 |
| WFC2418LB | \$ 238.38 |
| WFC3624 | \$ 289.47 |
| WFC3624G | \$ 312.17 |
| WFC3624LB | \$ 312.17 |
| WFC3630 | \$ 342.68 |
| WFC3630G | \$ 366.66 |
| WFC3630LB | \$ 366.66 |
| WFC3636 | \$ 411.23 |
| WFC3636G | \$ 439.99 |

| | |
|-----------|-----------|
| WFC3636LB | \$ 439.99 |
| WFC3648 | \$ 493.80 |
| WFC3648G | \$ 527.85 |
| WFC3648LB | \$ 527.85 |
| WFC3660 | \$ 591.37 |
| WFC3660G | \$ 632.75 |
| WFC3660LB | \$ 632.75 |
| WFC4872 | \$ 741.35 |
| WFC4872G | \$ 889.60 |
| WFC4872LB | \$ 889.60 |
| WFD2418 | \$ 297.89 |
| WFD2418G | \$ 318.74 |
| WFD2418LB | \$ 318.74 |
| WFD3624 | \$ 368.93 |
| WFD3624G | \$ 394.75 |
| WFD3624LB | \$ 394.75 |
| WFD3630 | \$ 409.43 |
| WFD3630G | \$ 438.10 |
| WFD3630LB | \$ 438.10 |
| WFD3636 | \$ 491.33 |
| WFD3636G | \$ 525.71 |
| WFD3636LB | \$ 525.71 |
| WFD3648 | \$ 554.85 |
| WFD3648G | \$ 593.69 |
| WFD3648LB | \$ 593.69 |
| WFD3660 | \$ 674.75 |
| WFD3660G | \$ 721.97 |
| WFD3660LB | \$ 721.97 |
| WFD4872 | \$ 835.54 |
| WFD4872G | \$ 894.03 |
| WFD4872LB | \$ 894.03 |
| WGB1824 | \$ 198.88 |
| WGB2436 | \$ 254.37 |
| WGB3648 | \$ 367.87 |
| WGB4848 | \$ 446.00 |
| WGB4872 | \$ 618.34 |
| WGB4896 | \$ 714.26 |
| WM-10B | \$ 98.24 |
| WM-10BK | \$ 82.01 |
| WM-10C | \$ 88.50 |
| WM-7B | \$ 87.62 |
| WM-7BK | \$ 71.40 |
| WM-7C | \$ 77.89 |
| WMC-7 | \$ 26.95 |
| WOC1218NT | \$ 22.22 |
| WOC1824 | \$ 32.28 |
| WOC1824NT | \$ 31.34 |

| | |
|-----------|-------------|
| WOC2436 | \$ 47.22 |
| WOC2436NT | \$ 45.85 |
| WOC3648 | \$ 79.61 |
| WOC3648NT | \$ 77.29 |
| WOC3660 | \$ 171.48 |
| WOC3660NT | \$ 166.49 |
| WOC4860 | \$ 218.24 |
| WOC4872 | \$ 246.96 |
| WOC4896 | \$ 318.41 |
| WOS1824 | \$ 70.91 |
| WOS2436 | \$ 124.16 |
| WOS3648 | \$ 226.91 |
| WOS3660 | \$ 345.37 |
| WOS48120 | \$ 768.40 |
| WOS48144 | \$ 895.95 |
| WOS48192 | \$ 1,344.74 |
| WOS4860 | \$ 392.52 |
| WOS4872 | \$ 463.03 |
| WOS4896 | \$ 606.00 |
| WP-36 | \$ 417.29 |
| WP-40 | \$ 556.39 |
| WP-48 | \$ 642.11 |
| WRBC3648 | \$ 417.76 |
| WRBC4260 | \$ 496.56 |
| WRBC4872 | \$ 559.62 |
| WRC3648 | \$ 349.06 |
| WRC4260 | \$ 433.69 |
| WRC4872 | \$ 458.81 |
| WRS3648 | \$ 568.55 |
| WRS4260 | \$ 695.47 |
| WRS4872 | \$ 786.70 |
| WVC-1 | \$ 1,430.19 |
| WVC-2 | \$ 1,841.74 |